HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 430A3160001

BRIDGE OWNER: HUMPHREYS COUNTY ROAD NAME: BAKERVILLE RD CROSSING: DUCK RIVER

> LATITUDE" N 36 04267 DEGREES

COUNTY: HUMPHREYS ROUTE: 00910 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 15.70

LON	NGITUDE: W 87.85362 DEGRE	ES	YEAR BUILT: 1945
		TYPE OF SUPERSTRUCTURE -	
MAIN SPAN:	STEEL - TRUSS - THRU	APPR. SPAN:	STEEL CONTINUOUS - STRINGER/MULTI-BEAM OR GIRDER
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT OF	N CONCRETE SPREAD FOOTING FOUN	NDATION
BENTS:	CONCRETE COLUMN TWO POST	BENT ON STEEL PILE FOUNDATION	
PIERS:	CONCRETE COLUMNS WITH SO	LID WEB WALL (DUMB BELL) ON STEE	EL PILE FOUNDATION
		SCOUR EVALUATION	
		es that extensive scour has occurr res. No scour countermeasures a	ed at bridge foundations. Immediate action re installed but they are needed.
		— INSPECTION PROCEDURES —	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Loca	I Maintenance Personnel
		[] THP or Local Law Enf	orcement Personnel
		[] Other:	
1. 0 2. 0 [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers of k pier exposure, if possible,	ion along curb line, both bridge pents.	
lf Closure is	recommended:		
Coun temp	nty or City Maintenance Pers	onnel. Use Barricade Tape, traf corists to stay off of the bridge ι	ured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance	Supervisor (if bridge is State	maintained)
	(2) City or County High	way Maintenance Official (if bri	idge is not State maintained)
	(3) Tennessee Highway	Patrol and/or local law enforcer	ment Officers as appropriate
	(4) TDOT Regional Brid	ge Engineer	
	ridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	vork with State District maintenance or local highway maintenance route. Any bridge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 296-7795		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 296-2121		
COUNTY SHERIFF'S OFFICE	(931) 296-2301		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct Latest Bridge Inspection Report	•		
Scour POA Report with the above Chec Bridge Design Plans, if available	KIIST		
Tape measure with weight			
Plumb bob			
Range Pole			
_	Barricade Tape printed with the following message:		
-	AZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24