## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: HUMPHREYS

BRIDGE ID NUMBER: 430A6000001

BRIDGE OWNER: CITY OF WAVERLY

ROAD NAME: S RAILROAD ST

CROSSING: TRACE CREEK

LATITUDE:: N 36.08572 DEGREES
LONGITUDE: W 87.79327 DEGREES

ROUTE: 0A298
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.05
YEAR BUILT: 1978

	т	YPE OF SUPERSTRUCTURE =	
MAIN SPAN:	PRESTRESSED CONCRETE CONTINUO STRINGER/MULTI-BEAM OR GIRDER		NOT APPLICABLE
		TYPE OF SUBSTRUCTURE =	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMENT ON CONCRETE PILE FOUNDATION		
BENTS:	NOT APPLICABLE		
PIERS:	PIERS: CONCRETE HAMMERHEAD PIER ON CONCRETE PILE FOUNDATION		
		SCOUR EVALUATION =	
	our critical; bridge foundations deter sures are installed but they are nee		culated scour conditions. No scour
		NSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
			al Maintenance Personnel
		[ ] THP or Local Law En	forcement Personnel
		[ ] Other:	
[ ] - Span 1. C 2. C [ ] - Chec [ ] - Chec [ ] - Revie	Check for plumb of piers or bents ck for embankment erosion ck for drift build-up on piers or be ck pier exposure, if possible, and ew the latest bridge inspection re	long curb line, both bridge. nts compare to previous inspe	
[ ] - Stay a Coun temp be pr	nty or City Maintenance Personne porary measures to warn motorist roperly closed and barricaded. act: (1) District Maintenance Sup (2) City or County Highway M	el. Use Barricade Tape, trans s to stay off of the bridge ervisor (if bridge is State Maintenance Official (if br	until such time as the bridge may
	(4) TDOT Regional Bridge Er	•	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in establishing a detour route. Any brid prior to signing the detour route.	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(931) 296-2101		
PUBLIC WORKS DIRECTOR	(931) 296-4732		
[ ] - Summarize and submit findings from the inspect The report shall include the date and time of the as appropriate, photographs of the bridge and s scouring has occurred, the report shall also be	e inspection, a brief summary of findings and, stream channel measurements. If significant		
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	on:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tap			
SAFETY HAZARD KEEP	AWAY		
A Barricade Tape Dispenser with serrated cutter			
A roll of Duct Tape			
Traffic Cones - Minimum of four (4)			
Traffic Safety Flares - Minimum of four (4) or set of ele	ectronic warning flashers		

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)**