## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 430A6100001

BRIDGE OWNER: HUMPHREYS COUNTY

ROAD NAME: SHIVER LN CROSSING: TRACE CREEK

COUNTY: HUMPHREYS ROUTE: 0A610 SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	ATITUDE:: N 36.12817 DEGREES NGITUDE: W 87.65967 DEGREES		
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/I		
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION -	
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
[ ] - Span	heck on a bridge during floods movement - horizontally as w Check displacement / deflectio		
2. (	Check for plumb of piers or be	nts.	
[ ] - Chec	k for embankment erosion		
[ ] - Check for drift build-up on piers or bents			
[ ] - Check pier exposure, if possible, and compare to previous inspection			
[ ] - Revie	ew the latest bridge inspection	report versus current field conditions	
If Closure is	recommended:		
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[ ] - Cont	act: (1) District Maintenance S	Supervisor ( if bridge is State maintained )	
	` , , ,	y Maintenance Official ( if bridge is not State maintained )	
		atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	-	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



<ul> <li>The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route.</li> </ul>	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 296-7795		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 296-2121		
COUNTY SHERIFF'S OFFICE	(931) 296-2301		
- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection  Latest Bridge Inspection Report  Control Board With the shorts Chaptering	on:		
Scour POA Report with the above Checklist Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:		
CAFETY HAZARD KEED			

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24