## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 430A6200001

BRIDGE OWNER: HUMPHREYS COUNTY ROAD NAME: DURHAM CEM LN

CROSSING: BRANCH

LATITUDE:: N 36.09092 DEGREES LONGITUDE: W 87.74250 DEGREES

COUNTY: HUMPHREYS ROUTE: 0A620 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.03

YEAR BUILT: 1983

201	10.11.05E. 11. 01.11.4200	12/11/ 36/21. 1300
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge has I	inknown foundations. Disk of soc	ur cannot be determined. The bridge shall be monitored for distress
		e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
	·	[ ] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[ ] Other:
Things to c	heck on a bridge during floods	<u>:</u>
[ ] - Span	movement - horizontally as w	ell as vertically
	-	n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	
	k for drift build-up on piers or	pents
	•	d compare to previous inspection
		report versus current field conditions
<u>lf Closure is</u>	recommended:	
Coun temp	nty or City Maintenance Persor	eross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[ ] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any l prior to signing the detour route.	bridge on the selected detour route shall be checked	
[ ] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(931) 296-7795	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 296-2121	
COUNTY SHERIFF'S OFFICE	(931) 296-2301	
as appropriate, photographs of the bridge an	the inspection, a brief summary of findings and, and stream channel measurements. If significant be copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Inspe	ction:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade		
SAFETY HAZARD KEE	PAWAY	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24