## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 43\$62230005

BRIDGE OWNER: HUMPHREYS COUNTY

ROAD NAME: BOLD SPRINGS RD

CROSSING: HURRICANE CREEK

LATITUDE:: N 36.03265 DEGREES

LONGITUDE: W 87.65598 DEGREES

COUNTY: HUMPHREYS
ROUTE: 00933
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 6.56
YEAR BUILT: 1956

		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE ————————————————————————————————————
	CONCRETE STUB ABUTMENT ON S	
BENTS:	CONCRETE COLUMN TWO POST B	
PIERS:	CONCRETE SOLID SHAFT PIER ON	ROCK FOUNDATION
		SCOUR EVALUATION
Bridge is sconeeded.	our critcal; Bridge has failed and	is closed to traffic. No scour countermeasures are installed but they are
		INSPECTION PROCEDURES
What Initiat	ed the Call-out Inspection?	[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
		[ ] •
Things to c	heck on a bridge during flood	s:
	<u> </u>	
	movement - horizontally as w	•
	<u>-</u>	n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	nts.
	k for embankment erosion	hauta
	k for drift build-up on piers or	
		nd compare to previous inspection
[ ] - Revie	ew the latest bridge inspection	report versus current field conditions
lf Closura is	recommended:	
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	Supervisor ( if bridge is State maintained )
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	_	ntil the water recedes and a daylight visual inspection is made
by a	TDOT bridge inspection team.	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	vork with State District maintenance or local highway maintenance route. Any bridge on the selected detour route shall be checked		
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 296-7795		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 296-2121		
COUNTY SHERIFF'S OFFICE	(931) 296-2301		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct  Latest Bridge Inspection Report	•		
Scour POA Report with the above Chec Bridge Design Plans, if available	KIIST		
Tape measure with weight			
Plumb bob			
Range Pole			
_	Barricade Tape printed with the following message:		
-	AZARD KEEP AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24