HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: JOHNSON

BRIDGE ID NUMBER: 460A0470001
BRIDGE OWNER: JOHNSON COUNTY
ROAD NAME: OLD HWY 67

CROSSING: DOE CREEK

LATITUDE:: N 36.39989 DEGREES LONGITUDE: W 81.96786 DEGREES

ROUTE: 0A047
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.36
YEAR BUILT: 1960

		TYPE OF SUPERSTRUCT	TIIDE _		
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM OF		SPAN:	NOT APPLICABLE	
		TYPE OF SUBSTRUCTU			
ABUTMENTS:		NT ON CONCRETE SPREA	D FOOTII	NG FOUNDATION	
BENTS:	NOT APPLICABLE				
PIERS:	CONCRETE SOLID SHAFT PIER ON	CONCRETE SPREAD FOO	TING FO	UNDATION	
		SCOUR EVALUATION	N -		
	ınknown foundations. Risk of sco icant flood events. Monitor bridge			bridge shall be monitored for distress termeasures.	
		INSPECTION PROCEDU	RES -		
What Initiat	ed the Call-out Inspection?	[] BridgeWatch A			
What initiated the San Sat inspection.		TDOT District or Local Maintenance Personnel			
				forcement Personnel	
		[] •			
Things to c	heck on a bridge during floods	:			
_	movement - horizontally as we				
		-	h hridae	e rails and outer edge of bridge deck.	
	Check for plumb of piers or ben	-	ii bilage	Trails and outer eage or bridge deck.	
	k for embankment erosion	10.			
	k for drift build-up on piers or b	nents			
	k pier exposure, if possible, an		ıs insne	ection	
	ew the latest bridge inspection	•	-		
[] - Kevic	w the latest bridge inspection	report versus current	i iicia c	onanions	
If Closure is	recommended:				
Coun temp	nty or City Maintenance Person	nel. Use Barricade Ta	ipe, traf	eured and properly closed by District, ific cones and/or traffic flares as until such time as the bridge may	
[] - Conta	act: (1) District Maintenance Su	upervisor (if bridge i	is State	maintained)	
	(2) City or County Highway	/ Maintenance Officia	ıl (if br	idge is not State maintained)	
	(3) Tennessee Highway Pa	trol and/or local law e	enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer			
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 				

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	with State District maintenance or local highway maintenance e. Any bridge on the selected detour route shall be checked			
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:			
COUNTY MAYOR'S OFFICE	(423) 727-9696			
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 727-7851			
COUNTY SHERIFF'S OFFICE	(423) 727-7761			
The report shall include the date and t as appropriate, photographs of the bri	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:				
Suggested List of Equipment to conduct the Latest Bridge Inspection Report	e Inspection:			
Scour POA Report with the above Checklist				
Bridge Design Plans, if available				
Tape measure with weight				
Plumb bob				
Range Pole				
	ricade Tape printed with the following message:			
SAFFTY HAZAF	RD KEEP AWAY			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24