## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 460A4090001

BRIDGE OWNER: JOHNSON COUNTY

ROAD NAME: LITTLE DRY RUN RD

CROSSING: ROAN CREEK

LATITUDE:: N 36.37547 DEGREES LONGITUDE: W 81.89380 DEGREES

COUNTY: JOHNSON
ROUTE: 0A409
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 4.35
YEAR BUILT: 1975

LON	NGITUDE: W 81.89380 DEGREES		YEAR BUILT: 1975
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	TYPE OF SUPERSTRUCTURE R GIRDER APPR. SPA	
ADJUTMENTO.	CONORETE FUIL LIFTOUT ABUTAGE	TYPE OF SUBSTRUCTURE	
	CONCRETE FULL HEIGHT ABUTME	NI ON UNKNOWN FOUNDATIO	N
BENTS: PIERS:	NOT APPLICABLE	LINKNOWN COUNDATION	
FIERO.	CONCRETE SOLID SHAFT PIER ON	UNKNOWN FOUNDATION	
		SCOUR EVALUATION	
	unknown foundations. Risk of sco icant flood events. Monitor bridge		he bridge shall be monitored for distress buntermeasures.
		INSPECTION PROCEDURES	
What Initiat	ed the Call-out Inspection?	[ ] BridgeWatch Alert	
	·		ocal Maintenance Personnel
		[ ] THP or Local Law	Enforcement Personnel
		[ ] Other:	
Things to c	heck on a bridge during floods	<u>s:</u>	
1. 0	movement - horizontally as w Check displacement / deflectio Check for plumb of piers or be	n along curb line, both bri	dge rails and outer edge of bridge deck.
	k for embankment erosion	113.	
	k for drift build-up on piers or	hants	
	k pier exposure, if possible, ar		snection
	ew the latest bridge inspection	•	-
[ ] - Kevic	w the latest bridge inspection	report versus current ner	a conditions
lf Closure is	recommended:		
Coun temp	nty or City Maintenance Persor	nel. Use Barricade Tape,	secured and properly closed by District, traffic cones and/or traffic flares as ge until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is St	ate maintained )
	(2) City or County Highwa	y Maintenance Official (i	f bridge is not State maintained )
	(3) Tennessee Highway P	atrol and/or local law enfo	rcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and	a daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	with State District maintenance or local highway maintenance e. Any bridge on the selected detour route shall be checked		
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 727-9696		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 727-7851		
COUNTY SHERIFF'S OFFICE	(423) 727-7761		
The report shall include the date and t as appropriate, photographs of the bri	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.  The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct the Latest Bridge Inspection Report	e Inspection:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	ricade Tape printed with the following message:		
SAFFTY HAZAF	RD KEEP AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24