## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 470D8130001

BRIDGE OWNER: KNOX COUNTY

ROAD NAME: FEDERAL RD

CROSSING: FRENCH BROAD RIVER
LATITUDE:: N 35.94862 DEGREES
LONGITUDE: W 83.84132 DEGREES

ROUTE: 0D813
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.24

COUNTY: KNOX

LON	NGITUDE: W 83.84132 DEGREES		YEAR BUILT: 1965
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX B GIRDERS - MULTIPLE	EAM OR APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE -	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON C	ONCRETE PILE FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	TWO ROWS OF CONCRETE PILES V	VITH A COMMON CAP ON CONCR	ETE PILE FOUNDATION
		SCOUR EVALUATION -	
	unknown foundations. Risk of sco iicant flood events. Monitor bridge		bridge shall be monitored for distress ntermeasures.
		INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Loca	al Maintenance Personnel
		[ ] THP or Local Law En	forcement Personnel
		[ ] Other:	
[ ] - Span 1. C 2. C [ ] - Chec [ ] - Chec	heck on a bridge during floods movement - horizontally as we Check displacement / deflection Check for plumb of piers or ben k for embankment erosion k for drift build-up on piers or l k pier exposure, if possible, an ew the latest bridge inspection	ell as vertically a along curb line, both bridg ts. pents d compare to previous insp	
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Person	nel. Use Barricade Tape, tra	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State	e maintained )
	(2) City or County Highway	/ Maintenance Official ( if b	ridge is not State maintained )
	(3) Tennessee Highway Pa	trol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	_	
	idge should remain closed until the water recedes and a daylight visual inspection is made		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ork with State District maintenance or local highway maintenance oute. Any bridge on the selected detour route shall be checked		
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(865) 215-2005		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(865) 215-5800		
COUNTY SHERIFF'S OFFICE	(865) 215-2432		
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.     </li> </ul>			
COMMENTS:			
Suggested List of Equipment to conduct	the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Check	list		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	Barricade Tape printed with the following message:		
SAFETY HA	ZARD KEEP AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24