HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 490A0330001

BRIDGE OWNER: LAUDERDALE COUNTY ROAD NAME: SHOAFS LANDING RD CROSSING: JONES SLOUGH

LATITUDE:: N 35.77128 DEGREES LONGITUDE: W 89.75056 DEGREES

COUNTY: LAUDERDALE ROUTE: 0A033 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.32

LON	NGITUDE: W 89.75056 DEGREES		YEAR BUILT: 1985
		TYPE OF SUPERSTRUCTURE -	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE =	
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FOU	NDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION -	
	unknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	·		al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
Things to c	heck on a bridge during floods	<u>::</u>	
[] - Span	movement - horizontally as we	ell as vertically	
1. C	Check displacement / deflection	n along curb line, both bridg	e rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or bei	nts.	
[] - Chec	k for embankment erosion		
[] - Chec	k for drift build-up on piers or	bents	
[] - Chec	k pier exposure, if possible, ar	d compare to previous insp	ection
[] - Revie	ew the latest bridge inspection	report versus current field c	onditions
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Person	nel. Use Barricade Tape, traf	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	maintained)		
	(2) City or County Highwa	y Maintenance Official (if br	ridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officia	•	te District maintenance or local highway maintenance ridge on the selected detour route shall be checked	
	he bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTA	CT PERSONNEL:	TELEPHONE NUMBER:	
COUNT	Y MAYOR'S OFFICE	(731) 635-3500	
HWY. C	CHIEF ADMINISTRATOR'S OFFICE	(731) 635-9251	
COUNT	TY SHERIFF'S OFFICE	(731) 635-1311	
The re as app	port shall include the date and time of the propriate, photographs of the bridge and	ection to BridgeWatch scour monitoring system. he inspection, a brief summary of findings and, I stream channel measurements. If significant e copied to Bridge Inspection Headquarters.	
COMMENTS:			
Suggested L	ist of Equipment to conduct the Inspec	tion:	
	e Inspection Report		
	Report with the above Checklist		
•	gn Plans, if available		
•	re with weight		
Plumb bob			
Range Pole	Ball of callons Balanthadaya Barris 1. 7	'an a mintal mith the fallaming many	
A 1000 Foot	• •	ape printed with the following message:	
	SAFETY HAZARD KEEF	AWAY	

TDOT two-way radio (State Personnel only) and/or cellular telephone TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

A roll of Duct Tape