## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 500A1150001 COUNTY: LAWRENCE
BRIDGE OWNER: LAWRENCE COUNTY ROUTE: 0A115

ROAD NAME: OAKS RD.

CROSSING: W FORK BUFFALO RIVER
LATITUDE:: N 35.38047 DEGREES
LONGITUDE: W 87.38172 DEGREES

ROUTE: 0A115
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.44
YEAR BUILT: 1984

| LOI   | NGITODE. W 67.36172 DEGREES  | •  |                                   | TEAN BOILT. 1964   |  |  |
|---|--|--|-----------------------------------|--|--|--|
|   |  | TYPE OF SUPE   | RSTRUCTURE -                      |  |  |  |
| MAIN SPAN:  | PRESTRESSED CONCRETE - BOX I<br>GIRDERS - MULTIPLE   | BEAM OR  | APPR. SPAN:                       | NOT APPLICABLE   |  |  |
|   |  | TYPE OF SUB  | STRUCTURE -                       |  |  |  |
| ABUTMENTS:  | CONCRETE STUB ABUTMENT ON U  | TUB ABUTMENT ON UNKNOWN FOUNDATION                                     |                                   |  |  |  |
| BENTS:  | TS: CONCRETE PILE BENT ON PILE FOUNDATION  |  |                                   |  |  |  |
| PIERS:  | NOT APPLICABLE   |  |                                   |  |  |  |
|   |  | SCOUR EVA  | ALUATION =                        |  |  |  |
|   | our critical; bridge foundations de<br>sures are installed but they are n  | etermined to be  |                                   | culated scour conditions. No scour   |  |  |
|   |  | INSPECTION P   | ROCEDURES -                       |  |  |  |
| What Initiated the Call-out Inspection                                |  | [ ] Bridge   | Watch Alert                       |  |  |  |
|   |  | [ ] TDOT [   | District or Loca                  | al Maintenance Personnel   |  |  |
|   |  | [ ] THP or   | Local Law Enf                     | forcement Personnel  |  |  |
|   |  | [ ] Other:   |                                   |  |  |  |
| [ ] - Span<br>1. (<br>2. (<br>[ ] - Chec<br>[ ] - Chec<br>[ ] - Revis | Check for plumb of piers or be<br>k for embankment erosion<br>k for drift build-up on piers or<br>k pier exposure, if possible, ar<br>w the latest bridge inspection | ell as vertically<br>n along curb li<br>nts.<br>bents<br>nd compare to | ne, both bridge<br>previous inspe |  |  |  |
| [ ] - Stay<br>Cour<br>temp  | nty or City Maintenance Persor   | nnel. Use Barri<br>rists to stay off                                   | cade Tape, traf                   | eured and properly closed by District, ific cones and/or traffic flares as until such time as the bridge may |  |  |
| -   | act: (1) District Maintenance S  |  | bridge is State                   | maintained )   |  |  |
| = <b>-</b>  | • •  | •  | _                                 | idge is not State maintained )   |  |  |
|   | (3) Tennessee Highway Pa   | atrol and/or lo  | cal law enforce                   | ment Officers as appropriate   |  |  |
|   | (4) TDOT Regional Bridge   | Engineer   |                                   |  |  |  |
|   | The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.                                   |  |                                   |  |  |  |

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



|   | ork with State District maintenance or local highway maintenance oute. Any bridge on the selected detour route shall be checked  |  |  |  |  |
|---|--|--|--|--|--|
|   | The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.  |  |  |  |  |
| CONTACT PERSONNEL:  | TELEPHONE NUMBER:  |  |  |  |  |
| COUNTY MAYOR'S OFFICE   | (931) 762-7700   |  |  |  |  |
| HWY. CHIEF ADMINISTRATOR'S OFFICE                                       | (931) 762-4272   |  |  |  |  |
| COUNTY SHERIFF'S OFFICE   | (931) 762-3626   |  |  |  |  |
| The report shall include the date ar as appropriate, photographs of the | - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. |  |  |  |  |
| COMMENTS:   |  |  |  |  |  |
| Suggested List of Equipment to conduct  Latest Bridge Inspection Report | the Inspection:  |  |  |  |  |
| Scour POA Report with the above Check                                   | list   |  |  |  |  |
| Bridge Design Plans, if available                                       |  |  |  |  |  |
| Tape measure with weight  |  |  |  |  |  |
| Plumb bob   |  |  |  |  |  |
| Range Pole  |  |  |  |  |  |
|   | Barricade Tape printed with the following message:   |  |  |  |  |
| SAFFTY HA   | ZARD KEEP AWAY   |  |  |  |  |

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24