## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 520A3700001
BRIDGE OWNER: LINCOLN COUNTY
ROAD NAME: WALKER CR
CROSSING: WALKER CREEK

LATITUDE:: N 35.02890 DEGREES
LONGITUDE: W 86.60185 DEGREES

COUNTY: LINCOLN
ROUTE: 0A370
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.17
YEAR BUILT: 1917

		TYPE OF SUPE	RSTRUCTURE =	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM OF		APPR. SPAN:	NOT APPLICABLE
BENTS:	CONCRETE FULL HEIGHT ABUTMEN NOT APPLICABLE		E SPREAD FOOTI	
PIERS:	CONCRETE SOLID SHAFT PIER ON	CONCRETE SPR	EAD FOOTING FO	UNDATION
	unknown foundations. Risk of sco icant flood events. Monitor bridge	in lieu of insta	etermined. The Illing scour coun	bridge shall be monitored for distress termeasures.
1871 4 1 141 4		INSPECTION P		
wnat initiat	ed the Call-out Inspection?	[ ] THP or	District or Loca Local Law En	al Maintenance Personnel forcement Personnel
Things to c	heck on a bridge during floods	:		
1. C 2. C [ ] - Chec [ ] - Chec	movement - horizontally as we Check displacement / deflection Check for plumb of piers or ben k for embankment erosion k for drift build-up on piers or b k pier exposure, if possible, an ew the latest bridge inspection	n along curb li nts. bents nd compare to	ine, both bridge	
lf Closure is	recommended:			
Coun temp	ity or City Maintenance Person	nel. Use Barri	cade Tape, trat	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if	bridge is State	maintained )
	(2) City or County Highway	y Maintenance	e Official ( if br	idge is not State maintained )
	` '		cal law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	•		
	Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.			

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[ ] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any br	ridge on the selected detour route shall be checked
[ ] - The bridge can be re-opened only after a TDO units and they are determined to be structural	
CONTACT PERSONNEL:	TELEPHONE NUMBER:
COUNTY MAYOR'S OFFICE	(931) 433-3045
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 433-2585
COUNTY SHERIFF'S OFFICE	(931) 433-3111
[ ] - Summarize and submit findings from the inspective The report shall include the date and time of the as appropriate, photographs of the bridge and scouring has occurred, the report shall also be COMMENTS:	ne inspection, a brief summary of findings and, I stream channel measurements. If significant e copied to Bridge Inspection Headquarters.
Suggested List of Equipment to conduct the Inspect	tion:
Latest Bridge Inspection Report	
Scour POA Report with the above Checklist Bridge Design Plans, if available	
Tape measure with weight	
Plumb bob	
Range Pole	
A 1000 Foot Roll of yellow Polyethylene Barricade To	ape printed with the following message:

**SAFETY HAZARD KEEP AWAY** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Cones - Minimum of four (4)

**PUBLICATION DATE** 

A roll of Duct Tape

07-Nov-24