HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: **52F00450003**BRIDGE OWNER: **LINCOLN COUNTY**ROAD NAME: **OLD HUNTSVILLE RD**

CROSSING: BRANCH

LATITUDE:: N 35.03362 DEGREES LONGITUDE: W 86.60115 DEGREES

COUNTY: LINCOLN
ROUTE: 01029
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.47
YEAR BUILT: 1977

		TYPE OF SUPE	DSTDUCTURE -	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O		APPR. SPAN:	NOT APPLICABLE
		7/25 05 011	OTD. 10T. 1D.F	
ADLITMENTS.	CONCRETE FULL HEIGHT ARLITME	TYPE OF SUB		INC FOLINDATION
	CONCRETE FULL HEIGHT ABUTME	NI ON CONCRE	E SPREAD FOOT	ING FOUNDATION
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EV	ALUATION -	
•	unknown foundations. Risk of sco icant flood events. Monitor bridge			bridge shall be monitored for distress termeasures.
		INSPECTION F	ROCEDURES -	
What Initiat	ed the Call-out Inspection?	[] Bridge	Watch Alert	
				al Maintenance Personnel
				forcement Personnel
Things to c	heck on a bridge during floods	<u>s:</u>		
[] - Snan	movement - horizontally as w	ell as verticall	v	
	•	,		e rails and outer edge of bridge deck.
	Check for plumb of piers or be	_	ine, both bridg	o rano ana oater cage or briage acon.
	k for embankment erosion	113.		
	k for drift build-up on piers or	hents		
	k pier exposure, if possible, ar		provious insp	action
	ew the latest bridge inspection	-		
[] - Revie	ew the latest bridge inspection	report versus	current neid d	conditions
If Closure is	recommended:			
		cross road un	til hridge is seg	cured and properly closed by District,
Cour temp	nty or City Maintenance Persor	nel. Use Barri ists to stay of	cade Tape, tra	ffic cones and/or traffic flares as until such time as the bridge may
-	act: (1) District Maintenance S		bridge is State	e maintained)
	• •	•	_	ridge is not State maintained)
	` ' '	•	•	ement Officers as appropriate
	(4) TDOT Regional Bridge			
[] - The E	``	•	ecedes and a	daylight visual inspection is made
	TDOT bridge inspection team			,

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any prior to signing the detour route.	bridge on the selected detour route shall be checked				
[] - The bridge can be re-opened only after a TD	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.				
CONTACT PERSONNEL:	TELEPHONE NUMBER:				
COUNTY MAYOR'S OFFICE	(931) 433-3045				
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 433-2585				
COUNTY SHERIFF'S OFFICE	(931) 433-3111				
	nd stream channel measurements. If significant be copied to Bridge Inspection Headquarters.				
Suggested List of Equipment to conduct the Inspe	ection:				
Latest Bridge Inspection Report					
Scour POA Report with the above Checklist					
Bridge Design Plans, if available					
Tape measure with weight					
Plumb bob					
Range Pole					
A 1000 Foot Roll of yellow Polyethylene Barricade	Tape printed with the following message:				

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

SAFETY HAZARD KEEP AWAY

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)