HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 54023190003
BRIDGE OWNER: McMINN COUNTY

ROAD NAME: EASTANALLEE VALLEY RD
CROSSING: MEADOW FORK CREEK
LATITUDE:: N 35.31123 DEGREES
LONGITUDE: W 84.71192 DEGREES

ROUTE: 02319
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 4.32
YEAR BUILT: 1938

COUNTY: McMINN

		TYPE OF SUPI	RSTRUCTURE -	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O		APPR. SPAN:	NOT APPLICABLE
			SSTRUCTURE -	
	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOW	N FOUNDATION	
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EV	ALUATION -	
				bridge shall be monitored for distress
during signif	icant flood events. Monitor bridge	e in lieu of insta	alling scour cour	ntermeasures.
		INSPECTION I	PROCEDURES -	
What Initiat	ed the Call-out Inspection?	[] Bridge	Watch Alert	
·		[] TDOT	District or Loca	al Maintenance Personnel
		[] THP o	r Local Law En	forcement Personnel
		[] Other:		
Things to c	heck on a bridge during floods	<u>s:</u>		
[] - Span	movement - horizontally as we	ell as vertical	v	
	•		-	e rails and outer edge of bridge deck.
	Check for plumb of piers or bei	_	, ,	
	k for embankment erosion			
	k for drift build-up on piers or	bents		
	k pier exposure, if possible, ar		previous insp	ection
	ew the latest bridge inspection	-	-	
	.	•		
<u>lf Closure is</u>	recommended:			
Coun temp	ity or City Maintenance Person	nnel. Use Barr ists to stay o	icade Tape, tra	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if	bridge is State	e maintained)
	(2) City or County Highwa	y Maintenanc	e Official (if b	ridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or lo	cal law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer		
	e Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance y bridge on the selected detour route shall be checked			
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:			
COUNTY MAYOR'S OFFICE	(423) 745-7634			
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 745-1820			
COUNTY SHERIFF'S OFFICE	(423) 745-5620			
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 				
COMMENTS:				
Suggested List of Equipment to conduct the Inspection Report Scour POA Report with the above Checklist	pection:			
Bridge Design Plans, if available				
Tape measure with weight				
Plumb bob				
Range Pole				
A 1000 Foot Roll of yellow Polyethylene Barricad	le Tape printed with the following message:			
CAEETY HAZADD M				

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24