HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 540A0570001
BRIDGE OWNER: McMINN COUNTY
ROAD NAME: MOSS RD

CROSSING: BIG SEWEE CREEK

LATITUDE:: N 35.61800 DEGREES

LONGITUDE: W 84.58567 DEGREES

COUNTY: McMINN
ROUTE: 0A632
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.11
YEAR BUILT: 1981

LON	NGITUDE: W 84.58567 DEGREES	YEAR BUILT: 1981
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - BOX GIRDERS - MULTIPLE	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		COOUR EVALUATION
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
	·	[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[] Other:
1. 0 2. 0 [] - Chec [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	n along curb line, both bridge rails and outer edge of bridge deck. nts.
[] - Stay a Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
-		
	` '	y Maintenance Official (if bridge is not State maintained)
	` ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	• • •
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



] - The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.			
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 745-7634		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 745-1820		
COUNTY SHERIFF'S OFFICE	(423) 745-5620		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection Report Scour POA Report with the above Checklist	pection:		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricad	le Tape printed with the following message:		
CAEETY HAZADD M			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24

BRIDGE ID 540A0570001