HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 540A1990001 BRIDGE OWNER: McMINN COUNTY ROAD NAME: N TOOMEY CROSSING

CROSSING: CANE CREEK

LATITUDE" N 35 33467 DEGREES

COUNTY: McMINN ROUTE: 0A199 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.10

LON	IGITUDE: W 84.51833 DEGREES	YEAR BUILT: 1973		
		TYPE OF SUPERSTRUCTURE		
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/I			
		TYPE OF SUBSTRUCTURE		
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON CONCRETE SPREAD FOOTING FOUNDATION		
BENTS:	ENTS: CONCRETE COLUMN FOUR OR MORE POST BENT ON CONCRETE SPREAD FOOTING FOUNDATION			
PIERS:	NOT APPLICABLE			
		COOLID EVALUATION		
5		SCOUR EVALUATION ————————————————————————————————————		
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.		
		INSPECTION PROCEDURES		
What Initiated the Call-out Inspection?		[] BridgeWatch Alert		
	·	[] TDOT District or Local Maintenance Personnel		
		[] THP or Local Law Enforcement Personnel		
		[] Other:		
1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, an	n along curb line, both bridge rails and outer edge of bridge deck. nts.		
[] - Stay a Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may		
[] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained)				
	` '	y Maintenance Official (if bridge is not State maintained)		
	.,,,	atrol and/or local law enforcement Officers as appropriate		
	(4) TDOT Regional Bridge	•••		
	The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	hing a detour route. Any bri	te District maintenance or local highway maintenance idge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEI	<u>.:</u>	TELEPHONE NUMBER:	
COUNTY MAYOR'S OF	FICE	(423) 745-7634	
HWY. CHIEF ADMINIST	RATOR'S OFFICE	(423) 745-1820	
COUNTY SHERIFF'S O	FICE	(423) 745-5620	
The report shall inc	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
Suggested List of Equipr	nent to conduct the Inspect	ion:	
Latest Bridge Inspection	Report		
Scour POA Report with the	ne above Checklist		
Bridge Design Plans, if a	vailable		
Tape measure with weigh	ıt		
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow	• •	ape printed with the following message:	
	SAFETY HAZARD KEEP	AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24