HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 540A3000003

BRIDGE OWNER: McMINN COUNTY

ROAD NAME: WESLEYANNA RD

CROSSING: TOM FOEMAN CREEK

LATITUDE:: N 35.35880 DEGREES

COUNTY: McMINN
ROUTE: 0A300
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.79
YEAR BUILT: 1981

LON	IGHUDE: W 84.57560 DEGREE	5		YEAR BUILT: 1981
		TYPE OF SUPER	STRUCTURE -	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX GIRDERS - MULTIPLE	BEAM OR	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBS	TRUCTURE -	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMI	ENT ON UNKNOWN	FOUNDATION	
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EVA	LUATION =	
	inknown foundations. Risk of sc icant flood events. Monitor bridg			bridge shall be monitored for distress termeasures.
		- INSPECTION PR	OCEDURES -	
What Initiat	ed the Call-out Inspection?	[] BridgeV	Vatch Alert	
	·	[] TDOT D	istrict or Loca	al Maintenance Personnel
		[] THP or I	Local Law Ent	orcement Personnel
		[] Other:		
[] - Span 1. 0 2. 0 [] - Chec [] - Chec [] - Chec	heck on a bridge during flood movement - horizontally as w Check displacement / deflection Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a ew the latest bridge inspection	vell as vertically on along curb linents. bents bents nd compare to p	orevious inspe	
f Closure is	recommended:			
Coun temp	ity or City Maintenance Perso	nnel. Use Barric rists to stay off	ade Tape, traf	eured and properly closed by District, ific cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if b	ridge is State	maintained)
	(2) City or County Highwa	ay Maintenance	Official (if br	idge is not State maintained)
	(3) Tennessee Highway P	atrol and/or loc	al law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer		
	Bridge should remain closed เ TDOT bridge inspection team.		ecedes and a d	daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	hing a detour route. Any bri	te District maintenance or local highway maintenance idge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEI	<u>.:</u>	TELEPHONE NUMBER:	
COUNTY MAYOR'S OF	FICE	(423) 745-7634	
HWY. CHIEF ADMINIST	RATOR'S OFFICE	(423) 745-1820	
COUNTY SHERIFF'S O	FICE	(423) 745-5620	
The report shall inc	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
Suggested List of Equipr	nent to conduct the Inspect	ion:	
Latest Bridge Inspection	Report		
Scour POA Report with the	ne above Checklist		
Bridge Design Plans, if a	vailable		
Tape measure with weigh	ıt		
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellov	• •	ape printed with the following message:	
	SAFETY HAZARD KEEP	AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24