HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 540A3470001
BRIDGE OWNER: McMINN COUNTY
ROAD NAME: TOM MARTIN RD
CROSSING: CHESTUEE CREEK

LATITUDE:: N 35.40953 DEGREES LONGITUDE: W 84.50508 DEGREES

COUNTY: McMINN
ROUTE: 0A347
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.86
YEAR BUILT: 1973

		TYPE OF SUPE	PSTPHCTHPE -	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O		APPR. SPAN:	NOT APPLICABLE
		TVDE OF CUE	CTRUCTURE	
ADLITMENTO.	CONODETE ELLE LIFECUT ADUTAGE	TYPE OF SUB		
	CONCRETE FULL HEIGHT ABUTME			IND ATION
BENTS:	CONCRETE COLUMN FOUR OR MC	RE POST BENT	ON UNKNOWN FO	UNDATION
PIERS:	NOT APPLICABLE			
		SCOUR EV	ALUATION =	
				bridge shall be monitored for distress
during signif	icant flood events. No scour cou	ntermeasures a	are installed but	they are needed.
		- INSPECTION F	ROCEDURES -	
What Initiat	ed the Call-out Inspection?	[] Bridge	Watch Alert	
				al Maintenance Personnel
				forcement Personnel
Things to c	heck on a bridge during floods	<u>s:</u>		
[] - Snan	movement - horizontally as w	ell as verticall	v	
			-	e rails and outer edge of bridge deck.
	Check for plumb of piers or be	•	o, both bridg	o rane and outer eage or strage acom
	k for embankment erosion			
	k for drift build-up on piers or	hents		
	k pier exposure, if possible, a		nrevious insn	ection
	ew the latest bridge inspection	-		
[] - IVevie	w the latest bridge inspection	report versus	current neia c	onutions
lf Closure is	recommended:			
[] - Stay	at bridge with vehicle pulled a	cross road un	til bridge is sec	cured and properly closed by District,
	-		-	ffic cones and/or traffic flares as
			f of the bridge	until such time as the bridge may
-	operly closed and barricaded.			
[] - Conta	act: (1) District Maintenance S	•	•	•
	` ' ' '	•	•	ridge is not State maintained)
	` '		cal law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	•		
	Bridge should remain closed u	e should remain closed until the water recedes and a daylight visual inspection is made		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	hing a detour route. Any bri	te District maintenance or local highway maintenance idge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEI	<u>.:</u>	TELEPHONE NUMBER:		
COUNTY MAYOR'S OF	FICE	(423) 745-7634		
HWY. CHIEF ADMINIST	RATOR'S OFFICE	(423) 745-1820		
COUNTY SHERIFF'S O	FICE	(423) 745-5620		
The report shall inc	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
Suggested List of Equipr	nent to conduct the Inspect	ion:		
Latest Bridge Inspection	Report			
Scour POA Report with the	ne above Checklist			
Bridge Design Plans, if a	vailable			
Tape measure with weigh	ıt			
Plumb bob				
Range Pole				
A 1000 Foot Roll of yellow	• •	ape printed with the following message:		
	SAFETY HAZARD KEEP	AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24