HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 540A3990001

BRIDGE OWNER: McMINN COUNTY

ROAD NAME: MEADOW FORK RD

CROSSING: MEADOW FORK BRANCH

LATITUDE:: N 35.31030 DEGREES

COUNTY: McMINN
ROUTE: 0A399
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.30
YEAR BUILT: 1973

LON	19110DL. W 64.09361 DEGREES	TEAR BOILT. 1973
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge has I	inknown foundations. Disk of soc	our cannot be determined. The bridge shall be monitored for distress
		e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES ————————————————————————————————————
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		Other:
Things to c	heck on a bridge during floods	<u>s:</u>
[] - Span	movement - horizontally as w	ell as vertically
		n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	
[] - Chec	k for drift build-up on piers or	bents
	• •	nd compare to previous inspection
[] - Review the latest bridge inspection report versus current field conditions		
	5 .	•
<u>lf Closure is</u>	recommended:	
Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance idge on the selected detour route shall be checked		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 745-7634		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 745-1820		
COUNTY SHERIFF'S OFFICE	(423) 745-5620		
 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 			
COMMENTS:			
Suggested List of Equipment to conduct the Inspect Latest Bridge Inspection Report	ion:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole	one wrinted with the following reseases:		
A 1000 Foot Roll of yellow Polyethylene Barricade Ta SAFETY HAZARD KEEP			
SAFELL HAZARU NEEP	AVVAI		

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)