HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 540A4210001
BRIDGE OWNER: McMINN COUNTY
ROAD NAME: BRITTON RD
CROSSING: OOSTANULA CREEK

LATITUDE:: N 35.31597 DEGREES
LONGITUDE: W 84.71322 DEGREES

COUNTY: McMINN
ROUTE: 0A421
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.20
YEAR BUILT: 1960

LON	IGITUDE: W 84.71322 DEGREES	•		YEAR BUILT: 1960
MAINI CDANI.		TYPE OF SUPERSTRU		NOT ADDITIONED F
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER AP	PR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUC	CTURE -	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON U	JNKNOWN FOUNDATIO	N	
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
		SCOUR EVALUAT	ION -	
	inknown foundations. Risk of sco icant flood events. Monitor bridge			bridge shall be monitored for distress termeasures.
		INSPECTION PROCE	DURES -	
What Initiat	ed the Call-out Inspection?	[] BridgeWatc	h Alert	
		[] TDOT Distri	ct or Loca	l Maintenance Personnel
		[] THP or Loca	al Law Enf	orcement Personnel
		[] Other:		
Things to c	<u>heck on a bridge during floods</u>	<u>s:</u>		
	movement - horizontally as w	•	oth bridge	e rails and outer edge of bridge deck.
	Check for plumb of piers or be	<u> </u>		o rane and cater cage of a rage accin
	k for embankment erosion			
	k for drift build-up on piers or	bents		
	k pier exposure, if possible, ar		ious inspe	ection
	ew the latest bridge inspection		-	
	5 .	•		
<u>f Closure is</u>	recommended:			
Coun temp	ity or City Maintenance Persor	nnel. Use Barricade rists to stay off of th	Tape, traf	ured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridg	je is State	maintained)
	(2) City or County Highwa	y Maintenance Offi	cial (if bri	idge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local la	w enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer		
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water reced	es and a d	laylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	hing a detour route. Any bri	te District maintenance or local highway maintenance idge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEI	<u>.:</u>	TELEPHONE NUMBER:		
COUNTY MAYOR'S OF	FICE	(423) 745-7634		
HWY. CHIEF ADMINIST	RATOR'S OFFICE	(423) 745-1820		
COUNTY SHERIFF'S O	FICE	(423) 745-5620		
The report shall inc	- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
Suggested List of Equipr	nent to conduct the Inspect	ion:		
Latest Bridge Inspection	Report			
Scour POA Report with the	ne above Checklist			
Bridge Design Plans, if a	vailable			
Tape measure with weigh	ıt			
Plumb bob				
Range Pole				
A 1000 Foot Roll of yellow	• •	ape printed with the following message:		
	SAFETY HAZARD KEEP	AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24