HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 540A5070001 BRIDGE OWNER: McMINN COUNTY

ROAD NAME: MONT HARMONY SHORT CREEK

CROSSING: ROGERS CREEK

LATITUDE: N 35 39901 DEGREES

ROUTE: 0A507 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 2.31

COUNTY: McMINN

LON	IGITUDE: W 84.77624 DEGREES	YEAR BUILT: 1981	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX GIRDERS - MULTIPLE		
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		CCOUR EVALUATION	
Delates has	al an after a letter a Diel after	SCOUR EVALUATION	
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	·	[] TDOT District or Local Maintenance Personnel	
		[] THP or Local Law Enforcement Personnel	
		[] Other:	
1. 0 2. 0 [] - Chec [] - Chec [] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a	n along curb line, both bridge rails and outer edge of bridge deck. nts.	
[] - Stay a Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
-			
. ,	` '	y Maintenance Official (if bridge is not State maintained)	
	.,,,	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	• • •	
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



] - The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.			
[] - The bridge can be re-opened only after a TDO units and they are determined to be structural	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 745-7634		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 745-1820		
COUNTY SHERIFF'S OFFICE	(423) 745-5620		
- Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspect Latest Bridge Inspection Report Scour POA Report with the above Checklist	tion:		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole	and and the Lord of the College Co.		
A 1000 Foot Roll of yellow Polyethylene Barricade Ta			

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape