HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 55015840001

BRIDGE OWNER: McNAIRY COUNTY

ROAD NAME: BULLMAN RD

CROSSING: SWEET LIPS CREEK

LATITUDE:: N 35,38086 DEGREES

ROUTE: 01584
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 3.85
YEAR BUILT: 1975

COUNTY: McNAIRY

LONGITUDE: W 88.52942 DEGREES TYPE OF SUPERSTRUCTURE = MAIN SPAN-**CONCRETE - CHANNEL BEAM** APPR. SPAN: NOT APPLICABLE TYPE OF SUBSTRUCTURE ABUTMENTS: TIMBER CAP ON TIMBER PILE FOUNDATION BENTS: TIMBER PILE BENT ON PILE FOUNDATION PIERS: **NOT APPLICABLE** SCOUR EVALUATION Bridge has unknown foundations. Risk of scour cannot be determined. The bridge shall be monitored for distress during significant flood events. Monitor bridge in lieu of installing scour countermeasures. **INSPECTION PROCEDURES** [] BridgeWatch Alert What Initiated the Call-out Inspection? [1 TDOT District or Local Maintenance Personnel [] THP or Local Law Enforcement Personnel [] Other: Things to check on a bridge during floods: [] - Span movement - horizontally as well as vertically 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck. 2. Check for plumb of piers or bents. [] - Check for embankment erosion [] - Check for drift build-up on piers or bents [] - Check pier exposure, if possible, and compare to previous inspection [] - Review the latest bridge inspection report versus current field conditions If Closure is recommended: [] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded. [] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained) (2) City or County Highway Maintenance Official (if bridge is not State maintained) (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate

PUBLICATION DATE

(4) TDOT Regional Bridge Engineer

by a TDOT bridge inspection team.

[] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance bridge on the selected detour route shall be checked
[] - The bridge can be re-opened only after a TI units and they are determined to be structu	DOT bridge inspection team checks the substructure urally stable.
CONTACT PERSONNEL:	TELEPHONE NUMBER:
COUNTY MAYOR'S OFFICE	(731) 645-3472
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 645-3651
COUNTY SHERIFF'S OFFICE	(731) 645-1000
The report shall include the date and time o as appropriate, photographs of the bridge a	spection to BridgeWatch scour monitoring system. If the inspection, a brief summary of findings and, and stream channel measurements. If significant be be copied to Bridge Inspection Headquarters.
COMMENTS:	
Suggested List of Equipment to conduct the Insp Latest Bridge Inspection Report	ection:
Scour POA Report with the above Checklist	
Bridge Design Plans, if available	
Tape measure with weight	
Plumb bob	
Range Pole	
A 1000 Foot Roll of yellow Polyethylene Barricade	e Tape printed with the following message:
SAFETY HAZARD KE	EP AWAY

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24