## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 550A1750003

BRIDGE OWNER: MCNAIRY COUNTY

ROAD NAME: WOLF PEN RD

CROSSING: TUSCUMBIA RIVER

LATITUDE:: N 35.01425 DEGREES LONGITUDE: W 88.73733 DEGREES

COUNTY: McNAIRY
ROUTE: 0A175
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.03
YEAR BUILT: 1984

LON	NGITUDE: W 88.73733 DEGREES	YEAR BUILT: 1984
MAIN SPAN:	PRESTRESSED CONCRETE - STRIN OR GIRDER	TYPE OF SUPERSTRUCTURE  GER/MULTI-BEAM APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS: BENTS:	CONCRETE STUB ABUTMENT ON C	ONCRETE PILE FOUNDATION
PIERS:	CONCRETE COLUMNS WITH SOLID	WEB WALL (DUMB BELL) ON CONCRETE PILE FOUNDATION
		SCOUR EVALUATION
	our critical; bridge foundations de ling scour countermeasures.	termined to be unstable for calculated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES
What Initiat	ed the Call-out Inspection?	[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[ ] Other:
[ ] - Span 1. 0 2. 0 [ ] - Chec [ ] - Chec	Check for plumb of piers or ber k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, an	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
<u>If Closure is</u>	recommended:	
Coun temp	nty or City Maintenance Person	eross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	State District maintenance or local highway maintenance bridge on the selected detour route shall be checked		
<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 645-3472		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 645-3651		
COUNTY SHERIFF'S OFFICE	(731) 645-1000		
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.     </li> </ul>			
COMMENTS:			
Suggested List of Equipment to conduct the Insp  Latest Bridge Inspection Report	ection:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade	e Tape printed with the following message:		
SAFETY HAZARD KE	EP AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24