HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 550A4950001 BRIDGE OWNER: McNAIRY COUNTY ROAD NAME: ROBERTS RD CROSSING: CYPRESS CREEK

COUNTY: McNAIRY ROUTE: 0A495 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 0.60

	NGITUDE:: N 35.14694 DEGREES NGITUDE: W 88.60239 DEGREES	YEAR BUILT: 1985
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - STRING OR GIRDER	
-		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON CO	ONCRETE PILE FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE HAMMERHEAD PIER ON	CONCRETE PILE FOUNDATION
		SCOUR EVALUATION
		ur cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. C 2. C [] - Chec [] - Chec [] - Revie	Check for plumb of piers or bench for embankment erosion ok for drift build-up on piers or be pier exposure, if possible, and ew the latest bridge inspection in	ell as vertically along curb line, both bridge rails and outer edge of bridge deck.
<u>If Closure is</u>	recommended:	
Coun temp	nty or City Maintenance Personi	ross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as sts to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance Su	pervisor (if bridge is State maintained)
	(2) City or County Highway	Maintenance Official (if bridge is not State maintained)
	``	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	_
	The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	work with State District maintenance or local highway maintenance route. Any bridge on the selected detour route shall be checked		
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 645-3472		
HWY. CHIEF ADMINISTRATOR'S OFFIC	E (731) 645-3651		
COUNTY SHERIFF'S OFFICE	(731) 645-1000		
The report shall include the date as appropriate, photographs of t	 Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters. 		
COMMENTS:			
Suggested List of Equipment to condu	uct the Inspection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Che	cklist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylen	e Barricade Tape printed with the following message:		
SAFETY H	IAZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24