## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



COUNTY: MADISON

BRIDGE ID NUMBER: 570A4790001 BRIDGE OWNER: MADISON COUNTY ROAD NAME: JOHN HOLT RD. CROSSING: BRANCH

**ROUTE: 0A479** SPECIAL CASE: 0 COUNTY SEQUENCE: 1

	TITUDE:: N 35.65194 DEGREES IGITUDE: W 88.61578 DEGREES	
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	WOOD OR TIMBER - STRINGER/MU GIRDER	LTI-BEAM OR APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
	TIMBER CAP ON TIMBER PILE FOU	
BENTS:	TIMBER PILE BENT ON PILE FOUN	DATION
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
	our critical; bridge foundations de sures are installed but they are n	etermined to be unstable for calculated scour conditions. No scour eeded.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
Things to c	heck on a bridge during floods	\$*
_		
	movement - horizontally as w Check displacement / deflection	n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	
	k for drift build-up on piers or	bents
[ ] - Chec	k pier exposure, if possible, ar	nd compare to previous inspection
[ ] - Revie	w the latest bridge inspection	report versus current field conditions
	recommended:	
Coun temp	ty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )
	` ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	y Maintenance Official ( if bridge is not State maintained )
		atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	_
	Bridge should remain closed until the water recedes and a daylight visual inspection is made	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[ ] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any prior to signing the detour route.	bridge on the selected detour route shall be checked	
- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 423-6020	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 422-1651	
COUNTY SHERIFF'S OFFICE	(731) 423-6000	
The report shall include the date and time of as appropriate, photographs of the bridge a	spection to BridgeWatch scour monitoring system.  of the inspection, a brief summary of findings and,  and stream channel measurements. If significant  o be copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Insp	pection:	
Latest Bridge Inspection Report Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricado	e Tape printed with the following message:	
SAFETY HAZARD KE	EEP AWAY	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24