## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 57\$R0010001

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: US70

CROSSING: CYPRESS CREEK

LATITUDE:: N 35.60483 DEGREES
LONGITUDE: W 89.02608 DEGREES

COUNTY: MADISON
ROUTE: SR001
SPECIAL CASE: 0
COUNTY SEQUENCE: 1

LOG MILE: 3.29
YEAR BUILT: 1925

LON	NGHODE. W 69.02006 DEGREE	TEAN BOILT. 1925	
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	INT ON SOIL FOUNDATION	
BENTS: CONCRETE PILE BENT ON PILE		DUNDATION	
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
	our critical; bridge foundations de sures are installed but they are r	etermined to be unstable for calculated scour conditions. No scour seeded.	
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
		[ ] TDOT District or Local Maintenance Personnel	
		[ ] THP or Local Law Enforcement Personnel	
		[ ] Other:	
2. C [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, a		
If Closure is	s recommended:		
Coun temp	nty or City Maintenance Persoi	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may	
[ ] - Conta	act: (1) District Maintenance S	Supervisor ( if bridge is State maintained )	
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )	
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer Engineer	
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[ ] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any brid	ge on the selected detour route shall be checked	
] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
REGION BRIDGE ENGINEER	(731) 234-9561	
DISTRICT MAINTENANCE SUPERVISOR	(731) 694-6673	
TENNESSEE HIGHWAY PATROL	(731) 423-6635	
The report shall include the date and time of the as appropriate, photographs of the bridge and st scouring has occurred, the report shall also be c	tream channel measurements. If significant copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Inspection	<u>n:</u>	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade Tap		
SAFETY HAZARD KEEP A	WAY	

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24