HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 58021650003
BRIDGE OWNER: MARION COUNTY
ROAD NAME: OLD DUNLAP RD
CROSSING: DANIEL CREEK

LATITUDE:: N 35.26076 DEGREES
LONGITUDE: W 85.48221 DEGREES

COUNTY: MARION
ROUTE: 01423
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 4.89
YEAR BUILT: 1941

201	TOTOBE. W CONTOLLY PLOTTER	
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	OR GIRDER APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	MASONRY OR CONCRETE BLOCK	ABUTMENTS ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress e in lieu of installing scour countermeasures.
		- INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during floods	<u>s:</u>
[] - Span	n movement - horizontally as w	vell as vertically
		on along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	
[] - Chec	k for drift build-up on piers or	bents
	• •	nd compare to previous inspection
		report versus current field conditions
		·
If Closure is	<u>s recommended:</u>	
Cour temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may.
• • •		Supervisor (if bridge is State maintained)
	(2) City or County Highwa	ay Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer
	Bridge should remain closed u TDOT bridge inspection team.	intil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour route. Any be prior to signing the detour route.	bridge on the selected detour route shall be checked	
[] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(423) 942-2552	
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 942-2581	
COUNTY SHERIFF'S OFFICE	(423) 942-2525	
as appropriate, photographs of the bridge an	the inspection, a brief summary of findings and, id stream channel measurements. If significant be copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to conduct the Inspec	ction:	
Latest Bridge Inspection Report		
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole	The second of the fall of the fall of the second of the se	
A 1000 Foot Roll of yellow Polyethylene Barricade SAFETY HAZARD KEE		
SAFELT HAZARD KEE	PAVAT	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24