HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 580A0940001

BRIDGE OWNER: CITY OF WHITWELL

ROAD NAME: S MAGNOLIA ST

CROSSING: SMALL BRANCH

LATITUDE:: N 35.18606 DEGREES
LONGITUDE: W 85.51572 DEGREES

COUNTY: MARION
ROUTE: 0A094
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.07
YEAR BUILT: 1921

LON	NGHODE: W 85.51572 DEGREES		YEAR BUILT: 1921
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
	unknown foundations. Risk of sco icant flood events. Monitor bridg		bridge shall be monitored for distress termeasures.
		- INSPECTION PROCEDURES -	
What Initiat	ed the Call-out Inspection?	[] BridgeWatch Alert	
	·		al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
Things to c	heck on a bridge during floods	<u>s:</u>	
1. (2. ([] - Chec	movement - horizontally as w Check displacement / deflectio Check for plumb of piers or be k for embankment erosion k for drift build-up on piers or	n along curb line, both bridg nts.	e rails and outer edge of bridge deck.
	k pier exposure, if possible, a		action
	ew the latest bridge inspection		
[] - Kevie	ew the latest bridge inspection	report versus current neid c	onditions
f Closure is	recommended:		
Coun temp	nty or City Maintenance Persor	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	e maintained)
	(2) City or County Highwa	y Maintenance Official (if bi	ridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ny bridge on the selected detour route shall be checked		
	dge can be re-opened only after a TDOT bridge inspection team checks the substructure nd they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
CITY MAYOR'S OFFICE	(423) 658-5151		
POLICE OFFICE	(423) 658-5151		
The report shall include the date and time as appropriate, photographs of the bridge	nspection to BridgeWatch scour monitoring system. of the inspection, a brief summary of findings and, and stream channel measurements. If significant so be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct the Ins	pection:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricae	de Tape printed with the following message:		
SAFETY HAZARD K	EEP AWAY		
A Barricade Tape Dispenser with serrated cutter	•		
A roll of Duct Tape			
Traffic Cones - Minimum of four (4)			
Traffic Safety Flares - Minimum of four (4) or set	of electronic warning flashers		

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)