HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 580A5110001
BRIDGE OWNER: MARION COUNTY
ROAD NAME: HENLEY COVE RD
CROSSING: BATTLE CREEK

LATITUDE:: N 35.16361 DEGREES

COUNTY: MARION
ROUTE: 0A511
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.00
YEAR BUILT: 1964

LON	NGITUDE: W 85.79006 DEGREES		YEAR BUILT: 1964
		TYPE OF SUPERSTRUCTURE -	
MAIN SPAN:	PRESTRESSED CONCRETE - BOX I GIRDERS - SINGLE OR SPREAD	BEAM OR APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON S	STEEL PILE FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE HAMMERHEAD PIER O	N STEEL PILE FOUNDATION	
		SCOUR EVALUATION =	
	our critical; bridge foundations de ling scour countermeasures.	etermined to be unstable for cal	culated scour conditions. Monitor bridge in
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	ош ило оши ош илоросион		al Maintenance Personnel
		[] THP or Local Law Ent	
[] - Span 1. C 2. C [] - Chec [] - Chec	heck on a bridge during floods movement - horizontally as we check displacement / deflection check for plumb of piers or bein k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, ar ew the latest bridge inspection	ell as vertically n along curb line, both bridge nts. bents nd compare to previous inspe	
<u>If Closure is</u>	recommended:		
Coun temp	nty or City Maintenance Person	nnel. Use Barricade Tape, traf	cured and properly closed by District, ific cones and/or traffic flares as until such time as the bridge may
[] - Contact: (1) District Maintenance Supervisor (if bridge is State maintained)			
	(2) City or County Highwa	y Maintenance Official (if br	idge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	e Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State I officials in establishing a detour route. Any bridge prior to signing the detour route. 				
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:			
COUNTY MAYOR'S OFFICE	(423) 942-2552			
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 942-2581			
COUNTY SHERIFF'S OFFICE	(423) 942-2525			
[] - Summarize and submit findings from the inspecting The report shall include the date and time of the inspection as appropriate, photographs of the bridge and structured scouring has occurred, the report shall also be considered.	inspection, a brief summary of findings and, ream channel measurements. If significant			
COMMENTS:				
Suggested List of Equipment to conduct the Inspection	<u>n:</u>			
Latest Bridge Inspection Report				
Scour POA Report with the above Checklist				
Bridge Design Plans, if available				
Tape measure with weight				
Plumb bob				
Range Pole				
A 1000 Foot Roll of yellow Polyethylene Barricade Tape				
SAFETY HAZARD KEEP AV	WAY			

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24