HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 58100240019 COUNTY: MARION BRIDGE OWNER: STATE OF TENNESSEE ROUTE: 10024 SPECIAL CASE: 0 ROAD NAME: 124 CROSSING: BIG FIERY GIZZARD CREEK COUNTY SEQUENCE: 1 LOG MILE: 11.43 LATITUDE:: N 35.10902 DEGREES YEAR BUILT: 1963 LONGITUDE: W 85,74502 **DEGREES** TYPE OF SUPERSTRUCTURE PRESTRESSED CONCRETE CONTINUOUS -APPR. SPAN: NOT APPLICABLE MAIN SPAN-STRINGER/MULTI-BEAM OR GIRDER TYPE OF SUBSTRUCTURE ABUTMENTS: CONCRETE STUB ABUTMENT ON STEEL PILE FOUNDATION BENTS: **NOT APPLICABLE** PIERS: CONCRETE HAMMERHEAD PIER ON STEEL PILE FOUNDATION **SCOUR EVALUATION** Bridge is scour critical; bridge foundations determined to be unstable for calculated scour conditions. Rip-rap protection has been installed and is in good condition. INSPECTION PROCEDURES What Initiated the Call-out Inspection? [] BridgeWatch Alert [] TDOT District or Local Maintenance Personnel [1 THP or Local Law Enforcement Personnel [] Other: Things to check on a bridge during floods: [] - Span movement - horizontally as well as vertically 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck. 2. Check for plumb of piers or bents. [] - Check for embankment erosion [] - Check for drift build-up on piers or bents [] - Check pier exposure, if possible, and compare to previous inspection [] - Review the latest bridge inspection report versus current field conditions If Closure is recommended: [] - Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District,

- J Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.
- [] Contact: (1) District Maintenance Supervisor (if bridge is State maintained)
 - (2) City or County Highway Maintenance Official (if bridge is not State maintained)
 - (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate
 - (4) TDOT Regional Bridge Engineer
- [] The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route. 	District maintenance or local highway maintenance lge on the selected detour route shall be checked
[] - The bridge can be re-opened only after a TDOT units and they are determined to be structurally	
CONTACT PERSONNEL:	TELEPHONE NUMBER:
REGION BRIDGE ENGINEER	(423) 290-7467
DISTRICT MAINTENANCE SUPERVISOR	(931) 434-1713
TENNESSEE HIGHWAY PATROL	(423) 634-6898
[] - Summarize and submit findings from the inspec The report shall include the date and time of the as appropriate, photographs of the bridge and s scouring has occurred, the report shall also be of	inspection, a brief summary of findings and, tream channel measurements. If significant
COMMENTS:	
Suggested List of Equipment to conduct the Inspection Latest Bridge Inspection Report Scour POA Report with the above Checklist	<u>on:</u>
Bridge Design Plans, if available	
Tape measure with weight	
Plumb bob	
Range Pole	
A 1000 Foot Roll of yellow Polyethylene Barricade Tap	pe printed with the following message:
CAEETY HAZADD KEED A	MAV

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24