## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 58100240038

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: 124

CROSSING: SEQUATCHIE RIVER

LATITUDE:: N 35.04863 DEGREES

LONGITUDE: W 85.62648 DEGREES

ROUTE: 10024
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 21.34

COUNTY: MARION

LON	IGITUDE: W 85.62648 DEGREES		YEAR BUILT: 1965	
		TYPE OF SUPERSTRUCTURE		
MAIN SPAN:	PRESTRESSED CONCRETE CONTI STRINGER/MULTI-BEAM OR GIRDE		NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE		
ABUTMENTS:	CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION			
BENTS:	NOT APPLICABLE			
PIERS:	CONCRETE HAMMERHEAD PIER O	N CONCRETE PILE FOUNDATION		
		SCOUR EVALUATION		
	our critical; bridge foundations de ing scour countermeasures.	etermined to be unstable for cal	culated scour conditions. Monitor bridge in	
		- INSPECTION PROCEDURES -		
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert		
	·	•	al Maintenance Personnel	
		[ ] THP or Local Law En	forcement Personnel	
		[ ] Other:		
[ ] - Span 1. C 2. C [ ] - Chec [ ] - Chec [ ] - Chec	heck on a bridge during floods movement - horizontally as we check displacement / deflection check for plumb of piers or being the for embankment erosion the for drift build-up on piers or the pier exposure, if possible, and the latest bridge inspection	ell as vertically n along curb line, both bridg nts. bents nd compare to previous inspe		
f Closure is	recommended:			
Coun temp	ty or City Maintenance Persor	nnel. Use Barricade Tape, trat rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may	
[ ] - Conta	ct: (1) District Maintenance Supervisor (if bridge is State maintained)			
	(2) City or County Highwa	y Maintenance Official ( if br	ridge is not State maintained )	
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer		
	] - The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.			

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(423) 290-7467		
DISTRICT MAINTENANCE SUPERVISOR	(931) 434-1713		
TENNESSEE HIGHWAY PATROL	(423) 634-6898		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspect	on:		
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta			
SAFETY HAZARD KEEP	AWAY		

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)