## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 60019260001
BRIDGE OWNER: MAURY COUNTY
ROAD NAME: WATER VALLEY RD.
CROSSING: BEECH CREEK

LATITUDE:: N 35.73562 DEGREES LONGITUDE: W 87.12992 DEGREES

COUNTY: MAURY
ROUTE: 01926
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.10
YEAR BUILT: 1940

LON	IGITUDE: W 87.12992 DEGREES	YEAR BUILT: 1940
MAIN OBAN		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON CONCRETE SPREAD FOOTING FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
•		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
	•	[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
Things to c	heck on a bridge during flood	<u>s:</u>
1. 0	movement - horizontally as w Check displacement / deflectio Check for plumb of piers or be	n along curb line, both bridge rails and outer edge of bridge deck.
	k for embankment erosion	its.
		hanta
	k for drift build-up on piers or	
		nd compare to previous inspection report versus current field conditions
[ ] - Revie	w the latest bridge inspection	report versus current neia conditions
If Closure is	recommended:	
Coun temp	ty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	upervisor ( if bridge is State maintained )
_		y Maintenance Official ( if bridge is not State maintained )
		atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	•••
	` '	ntil the water recedes and a daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ill work with State District maintenance or local highway maintenance our route. Any bridge on the selected detour route shall be checked ute.		
	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 375-1000		
HWY. CHIEF ADMINISTRATOR'S OFF	FICE (931) 375-6202		
COUNTY SHERIFF'S OFFICE	(931) 380-5733		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to con  Latest Bridge Inspection Report	iduct the Inspection:		
Scour POA Report with the above C	hecklist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	ene Barricade Tape printed with the following message:		
SAFFT	Y HAZARD KEEP AWAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24