HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 61022750011

BRIDGE OWNER: MEIGS COUNTY

ROAD NAME: OLD TEN MILE RD

CROSSING: HURRICANE CREEK

LATITUDE:: N 35.64260 DEGREES
LONGITUDE: W 84.67297 DEGREES

COUNTY: MEIGS
ROUTE: 0A066
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.09
YEAR BUILT: 1967

LON	NGITUDE: W 84.67297 DEGREES	3	YEAR BUILT: 1967
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM C	TYPE OF SUPERSTRUCTURE - R GIRDER APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE SOLID SHAFT PIER ON	UNKNOWN FOUNDATION	
		SCOUR EVALUATION	
	unknown foundations. Risk of so icant flood events. Monitor bridg		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
1. C 2. C [] - Chec [] - Chec	movement - horizontally as we check displacement / deflection check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, as we the latest bridge inspection	n along curb line, both bridg nts. bents nd compare to previous inspe	
<u>If Closure is</u>	recommended:		
Coun temp	ity or City Maintenance Persoi	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	maintained)
	(2) City or County Highwa	y Maintenance Official (if br	ridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer	
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance oridge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 334-5850		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 334-5157		
COUNTY SHERIFF'S OFFICE	(423) 334-5268		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to conduct the Inspec	ction:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade	Tape printed with the following message:		
SAFETY HAZARD KEE	P AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

17-Apr-19