HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 61S44290001

BRIDGE OWNER: MEIGS COUNTY

ROAD NAME: COTTONPART RD

CROSSING: GOODFIELD CREEK

LATITUDE:: N 35.49790 DEGREES

COUNTY: MEIGS
ROUTE: 01189
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.52

LON	IGITUDE: W 84.85120 DEGREES	3	YEAR BUILT: 1967
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/I	MULTI-BEAM OR APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE STUB ABUTMENT ON	STEEL PILE FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	CONCRETE HAMMERHEAD PIER O	N STEEL PILE FOUNDATION	
		SCOUR EVALUATION	
	our critical; bridge foundations de sures are installed but they are r		lculated scour conditions. No scour
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		-	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
Things to cl	heck on a bridge during flood	<u>s:</u>	
1. 0 2. 0 [] - Checl [] - Checl	movement - horizontally as we check displacement / deflection check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, and the latest bridge inspection	n along curb line, both bridg nts. bents nd compare to previous insp	
f Closure is	recommended:		
Coun temp	ty or City Maintenance Persor	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, Iffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	e maintained)
	(2) City or County Highwa	y Maintenance Official (if b	ridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforc	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	work with State District maintenance or local highway maintenance route. Any bridge on the selected detour route shall be checked		
 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructur units and they are determined to be structurally stable. 			
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 334-5850		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 334-5157		
COUNTY SHERIFF'S OFFICE	(423) 334-5268		
The report shall include the date a as appropriate, photographs of the	Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List of Equipment to conduct Latest Bridge Inspection Report Scour POA Report with the above Chec Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
_	e Barricade Tape printed with the following message:		
SAFETY H	A7ARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24