HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 650A1040001 BRIDGE OWNER: MORGAN COUNTY ROAD NAME: POTTER CHAPEL RD CROSSING: CLEAR CREEK

LATITUDE:: N 36.10207 DEGREES

COUNTY: MORGAN ROUTE: 0A104 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 5.94

LON	NGITUDE: W 84.71727 DEGREES	YEAR BUILT: 1970
		TYPE OF SUPERSTRUCTURE -
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/M	MULTI-BEAM OR APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON U	
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE SOLID SHAFT PIER ON	UNKNOWN FOUNDATION
		SCOUR EVALUATION
Duides has	unlun avum favum dationa. Diale af and	SCOUR EVALUATION ————————————————————————————————————
		our cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection		[] BridgeWatch Alert
	•	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
[] - Span 1. C 2. C [] - Chec [] - Chec	Check for plumb of piers or being the combankment erosion in the combankment erosion is for drift build-up on piers or the combands if possible, and the combands is possible.	ell as vertically n along curb line, both bridge rails and outer edge of bridge deck. nts.
<u>If Closure is</u>	recommended:	
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, anel. Use Barricade Tape, traffic cones and/or traffic flares as ists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	n will work with State District maintenance or local highway maintenance etour route. Any bridge on the selected detour route shall be checked route.		
	 The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable. 		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(423) 346-6288		
HWY. CHIEF ADMINISTRATOR'S	OFFICE (423) 346-6661		
COUNTY SHERIFF'S OFFICE	(423) 346-6262		
] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:			
Suggested List of Equipment to c	onduct the Inspection:		
Scour POA Report with the above	e Checklist		
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
	hylene Barricade Tape printed with the following message:		
SAFI	ETY HAZARD KEEP AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24