HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



COUNTY: MORGAN

BRIDGE ID NUMBER: 650A1110001 BRIDGE OWNER: MORGAN COUNTY ROAD NAME: BARNETT BRIDGE RD CROSSING: CLEAR CREEK

ROUTE: 0A111 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1.56

	NGITUDE:: N 36.12243 DEGREES NGITUDE: W 84.79465 DEGREES	YEAR BUILT: 1965
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/MU GIRDER	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMEN	T ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	CONCRETE SOLID SHAFT PIER ON U	INKNOWN FOUNDATION
		SCOUR EVALUATION
		ur cannot be determined. The bridge shall be monitored for distress in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiat	ted the Call-out Inspection?	[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
1. C 2. C [] - Chec [] - Chec [] - Chec	Check for plumb of piers or bent k for embankment erosion k for drift build-up on piers or b k pier exposure, if possible, and	along curb line, both bridge rails and outer edge of bridge deck.
<u>If Closure is</u>	recommended:	
Coun temp	nty or City Maintenance Personr	ross road until bridge is secured and properly closed by District, nel. Use Barricade Tape, traffic cones and/or traffic flares as sts to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance Su	pervisor (if bridge is State maintained)
	(2) City or County Highway	Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway Pat	trol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge B	Engineer
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



officials in		State District maintenance or local highway maintenance bridge on the selected detour route shall be checked	
	- The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT F	PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MA	AYOR'S OFFICE	(423) 346-6288	
HWY. CHIE	F ADMINISTRATOR'S OFFICE	(423) 346-6661	
COUNTY SH	HERIFF'S OFFICE	(423) 346-6262	
The report as approp] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.		
COMMENTS:			
Suggested List	of Equipment to conduct the Insp	ection:	
Latest Bridge In	spection Report		
Scour POA Rep	ort with the above Checklist		
Bridge Design F	Plans, if available		
Tape measure w	/ith weight		
Plumb bob			
Range Pole			
A 1000 Foot Rol	• •	e Tape printed with the following message:	
	SAFETY HAZARD KE	EP AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24