HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 650A2610001

BRIDGE OWNER: MORGAN COUNTY

ROAD NAME: LETORY RD

CROSSING: MUD CREEK

LATITUDE:: N 36.10728 DEGREES
LONGITUDE: W 84.57152 DEGREES

COUNTY: MORGAN
ROUTE: 0A261
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.43

LON	NGITUDE: W 84.57152 DEGREES		YEAR BUILT: 1971
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	TYPE OF SUPERSTRUCTURE = R GIRDER APPR. SPAN:	NOT APPLICABLE
ADUTMENTO		TYPE OF SUBSTRUCTURE =	
	CONCRETE FULL HEIGHT ABUTMENT ON UNKNOWN FOUNDATION		
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION -	
	unknown foundations. Risk of sco iicant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES =	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
		[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law Ent	forcement Personnel
			
Things to c	heck on a bridge during floods	<u>s:</u>	
[] - Span	movement - horizontally as w	ell as vertically	
	•	· ·	e rails and outer edge of bridge deck.
	Check for plumb of piers or be		
	k for embankment erosion		
	k for drift build-up on piers or	bents	
	k pier exposure, if possible, ar		ection
	ew the latest bridge inspection		
[]	on and larger zinage inspection.		
lf Closure is	recommended:		
Coun temp	nty or City Maintenance Person	nel. Use Barricade Tape, traf	cured and properly closed by District, ific cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	upervisor (if bridge is State	maintained)
_ -		· · · · · · · · · · · · · · · · · · ·	idge is not State maintained)
	``	•	ement Officers as appropriate
	(4) TDOT Regional Bridge		
[] - The F	()	· ·	daylight visual inspection is made
	by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



	officials in establishing a detour route. Any brid prior to signing the detour route.	dge on the selected detour route shall be checked		
[]		dge can be re-opened only after a TDOT bridge inspection team checks the substructure and they are determined to be structurally stable.		
	CONTACT PERSONNEL:	TELEPHONE NUMBER:		
	COUNTY MAYOR'S OFFICE	(423) 346-6288		
	HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 346-6661		
	COUNTY SHERIFF'S OFFICE	(423) 346-6262		
COM	The report shall include the date and time of the as appropriate, photographs of the bridge and s scouring has occurred, the report shall also be MENTS:	stream channel measurements. If significant copied to Bridge Inspection Headquarters.		
<u>Sug</u>	gested List of Equipment to conduct the Inspecti	on:		
Late	est Bridge Inspection Report			
Sco	ur POA Report with the above Checklist			
Brid	lge Design Plans, if available			
Тар	e measure with weight			
Plur	mb bob			
Ran	ge Pole			
A 10	000 Foot Roll of yellow Polyethylene Barricade Ta	pe printed with the following message:		
	SAFETY HAZARD KEEP	AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)