## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 66002640001

BRIDGE OWNER: STATE OF TENNESSEE ROAD NAME: KEN-TENN HWY

> CROSSING: NAPIER BRANCH LATITUDE:: N 36.44442 DEGREES

COUNTY: OBION ROUTE: SR214 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1.45

LON	NGITUDE: W 89.00242 DEGREE	S	YEAR BUILT: 1926
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	CONCRETE - TEE BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMENT ON TIMBER PILE FOUNDATION		
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION -	
		our cannot be determined. The le in lieu of installing scour count	bridge shall be monitored for distress termeasures.
		- INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert	
			I Maintenance Personnel
		[ ] THP or Local Law Enf	orcement Personnel
Things to c	heck on a bridge during flood	<u>s:</u>	
[ ] - Span	movement - horizontally as w	vell as vertically	
		·	e rails and outer edge of bridge deck.
	Check for plumb of piers or be		
	k for embankment erosion		
	k for drift build-up on piers or	bents	
	• •	nd compare to previous inspe	ection
		report versus current field co	
[ ]	on the latest shage meperale.	. roport volodo carroint noid ot	
If Closure is	recommended:		
Coun temp	ity or City Maintenance Perso	nnel. Use Barricade Tape, traf rists to stay off of the bridge <b>u</b>	ured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance	Supervisor (if bridge is State	maintained )
		ay Maintenance Official ( if br	-
	``	atrol and/or local law enforce	· · · · · · · · · · · · · · · · · · ·
	(4) TDOT Regional Bridge		• F F
[ ] - The F	``	•	laylight visual inspection is made
	TDOT bridge inspection team		, 5

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



<ul> <li>The bridge inspection team will work with State D officials in establishing a detour route. Any bridg prior to signing the detour route.</li> </ul>			
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
REGION BRIDGE ENGINEER	(731) 234-9561		
DISTRICT MAINTENANCE SUPERVISOR	(731) 571-8883		
TENNESSEE HIGHWAY PATROL	(901) 543-6256		
<ul> <li>Summarize and submit findings from the inspection         The report shall include the date and time of the in         as appropriate, photographs of the bridge and str         scouring has occurred, the report shall also be contained.</li> </ul>	nspection, a brief summary of findings and, eam channel measurements. If significant		
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	<u>:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tape	printed with the following message:		
SAFETY HAZARD KEEP AV	VAY		

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24