## **HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT**



BRIDGE ID NUMBER: 660A0580003 BRIDGE OWNER: OBION COUNTY ROAD NAME: FLIPPEN LN CROSSING: BRANCH

LATITUDE" N 36 42719 DEGREES

COUNTY: OBION ROUTE: 0A058 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 140

	IGITUDE: W 89.11781 DEGREE	
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	PRESTRESSED CONCRETE - BOX GIRDERS - MULTIPLE	
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE STUB ABUTMENT ON	STEEL PILE FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		cour cannot be determined. The bridge shall be monitored for distress ge in lieu of installing scour countermeasures.
-		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
[ ] - Span 1. C 2. C [ ] - Chec [ ] - Chec	Check for plumb of piers or be k for embankment erosion k for drift build-up on piers of k pier exposure, if possible, a	vell as vertically on along curb line, both bridge rails and outer edge of bridge deck. ents.
If Closure is	recommended:	
Coun temp	ity or City Maintenance Perso	across road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as prists to stay off of the bridge until such time as the bridge may
-		Supervisor ( if bridge is State maintained )
	(2) City or County Highw	ay Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway F	Patrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridg	e Engineer
	ridge should remain closed until the water recedes and a daylight visual inspection is made	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



offic		te District maintenance or local highway maintenance idge on the selected detour route shall be checked	
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONT	ACT PERSONNEL:	TELEPHONE NUMBER:	
COUN	NTY MAYOR'S OFFICE	(731) 885-9611	
HWY.	CHIEF ADMINISTRATOR'S OFFICE	(731) 885-5960	
COUN	ITY SHERIFF'S OFFICE	(731) 885-5832	
The r	eport shall include the date and time of the propriate, photographs of the bridge and	ection to BridgeWatch scour monitoring system. see inspection, a brief summary of findings and, stream channel measurements. If significant copied to Bridge Inspection Headquarters.	
COMMENTS			
<u>Suggested</u>	List of Equipment to conduct the Inspect	ion:	
	ge Inspection Report		
	Report with the above Checklist		
_	ign Plans, if available		
-	ure with weight		
Plumb bob			
Range Pole		one printed with the following message:	
A IUUU FOO	ot Roll of yellow Polyethylene Barricade Ta SAFETY HAZARD KEEP		
	SAFELL HAZARD NEEP	AVAI	

**TDOT radio directory (State Personnel only)** 

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape