HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 660A1530001 BRIDGE OWNER: OBION COUNTY ROAD NAME: N. BETHLEHEM RD. CROSSING: BRANCH

LATITUDE" N 36 45883 DEGREES

ROUTE: 0A153 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 1.82

COUNTY: OBION

	IGITUDE: W 89.02300 DEGREE	S YEAR BUILT: 1975
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	TIMBER CAP ON TIMBER PILE FO	UNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
		our cannot be determined. The bridge shall be monitored for distress je in lieu of installing scour countermeasures.
		- INSPECTION PROCEDURES
What Initiate	ed the Call-out Inspection?	[] BridgeWatch Alert
vviiat iiiitiat	ed the Gan-out mapechon:	[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to cl	<u>heck on a bridge during flood</u>	<u>s:</u>
[] - Span	movement - horizontally as w	vell as vertically
1. C	Check displacement / deflection	on along curb line, both bridge rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or be	ents.
	k for embankment erosion	
	k for drift build-up on piers or	
		nd compare to previous inspection
[] - Revie	ew the latest bridge inspection	report versus current field conditions
lf Closure is	recommended:	
		cross road until bridge is secured and properly closed by District,
Coun temp	ity or City Maintenance Perso	nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	ay Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway F	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour prior to signing the detour route	route. Any bridge on the selected detour route shall be checked	
[] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 885-9611	
HWY. CHIEF ADMINISTRATOR'S OFFICE	E (731) 885-5960	
COUNTY SHERIFF'S OFFICE	(731) 885-5832	
as appropriate, photographs of t	and time of the inspection, a brief summary of findings and, he bridge and stream channel measurements. If significant rt shall also be copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to condu	ict the Inspection:	
Latest Bridge Inspection Report		
Scour POA Report with the above Che	cklist	
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
	e Barricade Tape printed with the following message:	
SAFFTY H	IAZARD KEEP AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24