HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 660A3480001

BRIDGE OWNER: OBION COUNTY

ROAD NAME: OLD RIVER RD

CROSSING: HOOSIER CREEK

COUNTY: OBION
ROUTE: 0A348
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.46
YEAR BUILT: 1994

	TITUDE:: N 36.38944 DEGREE IGITUDE: W 89.07628 DEGREE		LOG MILE: 0.46 YEAR BUILT: 1994		
		TYPE OF SUPERSTRUCTURE			
MAIN SPAN:	PRESTRESSED CONCRETE CONT BEAM OR GIRDERS - MULTIPLE		NOT APPLICABLE		
		TYPE OF SUBSTRUCTURE -			
	S: CONCRETE STUB ABUTMENT ON CONCRETE PILE FOUNDATION				
BENTS:		CONCRETE PILE BENT ON PILE FOUNDATION			
PIERS:	NOT APPLICABLE				
		SCOUR EVALUATION			
event. Deter			the risk of bridge failure during a flood OOT for assessment. Rip-rap protection has		
		 INSPECTION PROCEDURES 			
What Initiated the Call-out Inspection?		[] BridgeWatch Alert			
		[] TDOT District or Loca	al Maintenance Personnel		
		[] THP or Local Law Ent	forcement Personnel		
		[] Other:			
		_			
Things to c	heck on a bridge during flood	<u>ls:</u>			
	movement - horizontally as v	•			
	<u>-</u>		e rails and outer edge of bridge deck.		
	Check for plumb of piers or be	ents.			
	k for embankment erosion				
	k for drift build-up on piers o				
		and compare to previous inspe			
[] - Revie	ew the latest bridge inspection	n report versus current field c	onditions		
<u>lf Closure is</u>	recommended:				
Coun temp	ty or City Maintenance Perso	nnel. Use Barricade Tape, traf prists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may		
[] - Conta	act: (1) District Maintenance	Supervisor (if bridge is State	maintained)		
	(2) City or County Highw	ay Maintenance Official (if br	ridge is not State maintained)		
		Patrol and/or local law enforce	ement Officers as appropriate		
	(4) TDOT Regional Bridg	e Engineer			
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.				

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	te District maintenance or local highway maintenance ridge on the selected detour route shall be checked		
	ge can be re-opened only after a TDOT bridge inspection team checks the substructure d they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 885-9611		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 885-5960		
COUNTY SHERIFF'S OFFICE	(731) 885-5832		
 Summarize and submit findings from the inspection. The report shall include the date and time of the as appropriate, photographs of the bridge and scouring has occurred, the report shall also be 	ne inspection, a brief summary of findings and, I stream channel measurements. If significant		
COMMENTS:			
·			
Suggested List of Equipment to conduct the Inspect	<u>tion:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade To	ape printed with the following message:		
SAFETY HAZARD KEEP	AWAY		
A Barricade Tape Dispenser with serrated cutter			
A roll of Duct Tape			
Traffic Cones - Minimum of four (4)			

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)