HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 660A4450001 BRIDGE OWNER: OBION COUNTY

ROAD NAME: S. GARRETT SAWMILL RD.

CROSSING: BRANCH

LATITUDE" N 36 34153 DEGREES

COUNTY: OBION ROUTE: 0A445 SPECIAL CASE: 0 COUNTY SEQUENCE: 1 LOG MILE: 3.69

LON	NGITUDE: W 89.05481 DEGREE	S	YEAR BUILT: 1970
		TYPE OF SUPERSTRUCTURE	
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM (NOT APPLICABLE
		TYPE OF CUPCTRUCTUPE	
ADLITMENTS:	CONCRETE FULL HEIGHT ABUTM	TYPE OF SUBSTRUCTURE =	
BENTS:	NOT APPLICABLE	ENT ON UNKNOWN FOUNDATION	
PIERS:	NOT APPLICABLE		
TILINO.	NOT AFFLICABLE		
		SCOUR EVALUATION -	
•	ınknown foundations. Risk of so icant flood events. Monitor bridg		bridge shall be monitored for distress termeasures.
		- INSPECTION PROCEDURES -	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
	•	[] TDOT District or Loca	al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
		[] Other:	
1. 0 2. 0 [] - Chec [] - Chec [] - Chec	movement - horizontally as we check displacement / deflection check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, as we the latest bridge inspection	on along curb line, both bridgents. bents nd compare to previous inspe	
f Closure is	recommended:		
Coun temp	nty or City Maintenance Perso	nnel. Use Barricade Tape, trat rists to stay off of the bridge	eured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance	Supervisor (if bridge is State	maintained)
	(2) City or County Highwa	ay Maintenance Official (if br	idge is not State maintained)
	(3) Tennessee Highway F	atrol and/or local law enforce	ment Officers as appropriate
	(4) TDOT Regional Bridge	e Engineer	
	- The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route. 	e District maintenance or local highway maintenance dge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 885-9611		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 885-5960		
COUNTY SHERIFF'S OFFICE	(731) 885-5832		
 Summarize and submit findings from the inspect The report shall include the date and time of the as appropriate, photographs of the bridge and s scouring has occurred, the report shall also be 	e inspection, a brief summary of findings and, stream channel measurements. If significant		
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	on:		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Ta			
SAFETY HAZARD KEEP	AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24