HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 660A5500003
BRIDGE OWNER: OBION COUNTY
ROAD NAME: CONCORD RD
CROSSING: GRASS CREEK

LATITUDE:: N 36.22317 DEGREES LONGITUDE: W 89.04853 DEGREES

COUNTY: OBION
ROUTE: 0A550
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 1.91
YEAR BUILT: 2002

LON	NGITUDE: W 89.04853 DEGREES	}	YEAR BUILT: 2002
MAIN SPAN:	CONCRETE - BOX BEAM OR GIRDE	TYPE OF SUPERSTRUCTURE RS - MULTIPLE APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION	
	unknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress ntermeasures.
		INSPECTION PROCEDURES	
What Initiated the Call-out Inspection?		[] BridgeWatch Alert	
			al Maintenance Personnel
		[] THP or Local Law En	forcement Personnel
Things to c	heck on a bridge during floods	<u>s:</u>	
1. (2. (Check for plumb of piers or be	n along curb line, both bridg	e rails and outer edge of bridge deck.
	k for embankment erosion	hanta	
	k for drift build-up on piers or		antinu
	k pier exposure, if possible, ar		
[] - Revie	ew the latest bridge inspection	report versus current field of	conditions
lf Clasura is	recommended:		
Coun temp	nty or City Maintenance Persor	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State	e maintained)
	(2) City or County Highwa	y Maintenance Official (if b	ridge is not State maintained)
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer	
	Bridge should remain closed until the water recedes and a daylight visual inspection is made TDOT bridge inspection team.		

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



 The bridge inspection team will work with State officials in establishing a detour route. Any brid prior to signing the detour route. 	District maintenance or local highway maintenance ge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 885-9611		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 885-5960		
COUNTY SHERIFF'S OFFICE	(731) 885-5832		
 Summarize and submit findings from the inspect The report shall include the date and time of the as appropriate, photographs of the bridge and st scouring has occurred, the report shall also be of 	inspection, a brief summary of findings and, ream channel measurements. If significant		
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	<u>n:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tap			
SAFETY HAZARD KEEP A	WAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24