## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 660A6930003
BRIDGE OWNER: OBION COUNTY
ROAD NAME: JACKSON HILL RD

CROSSING: BRANCH

LATITUDE:: N 36.27622 DEGREES LONGITUDE: W 89.32547 DEGREES

COUNTY: OBION
ROUTE: 0A693
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.52
YEAR BUILT: 1981

LON	IGITUDE: W 89.32547 DEGREES		YEAR BUILT: 1981
		TYPE OF SUPERSTRUCTURE -	
MAIN SPAN:	CONCRETE - CHANNEL BEAM	APPR. SPAN:	NOT APPLICABLE
		TYPE OF SUBSTRUCTURE	
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION	
BENTS:	NOT APPLICABLE		
PIERS:	NOT APPLICABLE		
		SCOUR EVALUATION =	
	inknown foundations. Risk of sco icant flood events. Monitor bridge		bridge shall be monitored for distress termeasures.
		INSPECTION PROCEDURES -	
What Initiate	ed the Call-out Inspection?	[ ] BridgeWatch Alert	
	•	[ ] TDOT District or Loca	al Maintenance Personnel
		[ ] THP or Local Law Ent	forcement Personnel
		[ ] Other:	
Things to cl	<u>heck on a bridge during floods</u>	<u>s:</u>	
1. C 2. C	movement - horizontally as w Check displacement / deflectio Check for plumb of piers or be k for embankment erosion	n along curb line, both bridge	e rails and outer edge of bridge deck.
	k for drift build-up on piers or	hants	
	k pier exposure, if possible, ar		ection
	ew the latest bridge inspection	• • • • • • • • • • • • • • • • • • • •	
[ ] - IVEAIC	w the latest bridge mapection	report versus current neid c	onutions
f Closure is	recommended:		
Coun temp	ity or City Maintenance Persor	nnel. Use Barricade Tape, traf	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may
[ ] - Conta	act: (1) District Maintenance S	supervisor ( if bridge is State	maintained )
	(2) City or County Highwa	y Maintenance Official ( if br	ridge is not State maintained )
	(3) Tennessee Highway Pa	atrol and/or local law enforce	ement Officers as appropriate
	(4) TDOT Regional Bridge		
	Bridge should remain closed u	ntil the water recedes and a d	daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



<ul> <li>The bridge inspection team will work with State officials in establishing a detour route. Any bridge prior to signing the detour route.</li> </ul>	District maintenance or local highway maintenance ge on the selected detour route shall be checked		
	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(731) 885-9611		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(731) 885-5960		
COUNTY SHERIFF'S OFFICE	(731) 885-5832		
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.     </li> </ul>			
COMMENTS:			
Suggested List of Equipment to conduct the Inspection	<u>n:</u>		
Latest Bridge Inspection Report			
Scour POA Report with the above Checklist			
Bridge Design Plans, if available			
Tape measure with weight			
Plumb bob Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade Tape	e printed with the following message:		
SAFETY HAZARD KEEP A			

**PUBLICATION DATE** 

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

**TDOT radio directory (State Personnel only)** 

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24