HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 660A8100003

BRIDGE OWNER: OBION COUNTY

ROAD NAME: OLD TURNPIKE RD

CROSSING: OVERFLOW (GWMA)

LATITUDE:: N 36.26494 DEGREES

COUNTY: OBION
ROUTE: 02122
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 4.42
YEAR BUILT: 1989

LON	NGHODE: W 69.11700 DEGREES	TEAN BOILT. 1909
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	CONCRETE - BOX BEAM OR GIRDE	ERS - MULTIPLE APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	ENT ON UNKNOWN FOUNDATION
BENTS:	CONCRETE PILE BENT ON PILE FO	DUNDATION
PIERS:	NOT APPLICABLE	
		CCOUR EVALUATION
Dalata da a sa	a a self-rel helder for a left-rel de	SCOUR EVALUATION
	our critical; bridge foundations de stalled and is in good condition.	etermined to be unstable for calculated scour conditions. Rip-rap protection
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[] BridgeWatch Alert
		[] TDOT District or Local Maintenance Personnel
		[] THP or Local Law Enforcement Personnel
		[] Other:
Things to c	heck on a bridge during floods	<u>s:</u>
[] - Span	movement - horizontally as w	ell as vertically
		n along curb line, both bridge rails and outer edge of bridge deck.
2. 0	Check for plumb of piers or be	nts.
[] - Chec	k for embankment erosion	
[] - Chec	k for drift build-up on piers or	bents
[] - Chec	k pier exposure, if possible, a	nd compare to previous inspection
[] - Revie	ew the latest bridge inspection	report versus current field conditions
<u>If Closure is</u>	<u>recommended:</u>	
Coun temp	nty or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[] - Conta	act: (1) District Maintenance S	Supervisor (if bridge is State maintained)
	(2) City or County Highwa	y Maintenance Official (if bridge is not State maintained)
	(3) Tennessee Highway P	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT

[] - The bridge inspection team will work with State District maintenance or local highway maintenance



officials in establishing a detour prior to signing the detour route	route. Any bridge on the selected detour route shall be checked	
[] - The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
COUNTY MAYOR'S OFFICE	(731) 885-9611	
HWY. CHIEF ADMINISTRATOR'S OFFICE	E (731) 885-5960	
COUNTY SHERIFF'S OFFICE	(731) 885-5832	
as appropriate, photographs of t	and time of the inspection, a brief summary of findings and, he bridge and stream channel measurements. If significant rt shall also be copied to Bridge Inspection Headquarters.	
Suggested List of Equipment to condu	ict the Inspection:	
Latest Bridge Inspection Report		
Scour POA Report with the above Che	cklist	
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
	e Barricade Tape printed with the following message:	
SAFFTY H	IAZARD KEEP AWAY	

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24