## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 67F00010001
BRIDGE OWNER: OVERTON COUNTY
ROAD NAME: UPPER HILHAM RD
CROSSING: FLAT CREEK

LATITUDE:: N 36.41168 DEGREES
LONGITUDE: W 85.37493 DEGREES

COUNTY: OVERTON
ROUTE: 01178
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 3.12
YEAR BUILT: 1940

LON	1911 ODE. W 65.37493 DEGREES	TEAR BOILT. 1940
		TYPE OF SUPERSTRUCTURE
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM O	R GIRDER APPR. SPAN: NOT APPLICABLE
-		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTME	NT ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge has I	inknown foundations. Risk of soc	our cannot be determined. The bridge shall be monitored for distress
		e in lieu of installing scour countermeasures.
		- INSPECTION PROCEDURES -
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		THP or Local Law Enforcement Personnel
		[ ] Other:
Things to c	heck on a bridge during floods	<u>s:</u>
[ ] - Span	movement - horizontally as w	ell as vertically
		n along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	
	k for drift build-up on piers or	bents
	• •	nd compare to previous inspection
		report versus current field conditions
<u>lf Closure is</u>	recommended:	
Coun temp	ity or City Maintenance Persor	cross road until bridge is secured and properly closed by District, nnel. Use Barricade Tape, traffic cones and/or traffic flares as rists to stay off of the bridge until such time as the bridge may
[ ] - Contact: (1) District Maintenand		Supervisor ( if bridge is State maintained )
	(2) City or County Highwa	y Maintenance Official ( if bridge is not State maintained )
	(3) Tennessee Highway Pa	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	Engineer Engineer
	Bridge should remain closed u TDOT bridge inspection team.	ntil the water recedes and a daylight visual inspection is made

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ate District maintenance or local highway maintenance oridge on the selected detour route shall be checked		
[ ] - The bridge can be re-opened only after a TDC units and they are determined to be structural	<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFFICE	(931) 823-5638		
HWY. CHIEF ADMINISTRATOR'S OFFICE	(931) 823-5631		
COUNTY SHERIFF'S OFFICE	(931) 823-5635		
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.</li> <li>The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.</li> </ul>			
COMMENTS:			
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report Scour POA Report with the above Checklist Bridge Design Plans, if available	ction:		
Tape measure with weight			
Plumb bob			
Range Pole			
A 1000 Foot Roll of yellow Polyethylene Barricade	Гаре printed with the following message:		
SAFETY HAZARD KEE	Ρ ΔWΔΥ		

TDOT radio directory (State Personnel only)

Traffic Cones - Minimum of four (4)

A Barricade Tape Dispenser with serrated cutter

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

A roll of Duct Tape