## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 67SR0840005

BRIDGE OWNER: STATE OF TENNESSEE

ROAD NAME: **SR84**CROSSING: **BRANCH** 

COUNTY: OVERTON
ROUTE: SR084
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 10.16

Ι.Λ	ATITUDE:: N 36.32724 DEGREE	S LOG MILE: 10.16
	NGITUDE: W 85.30375 DEGREE	
		TYPE OF SUPERSTRUCTURE
MAINI CDANI.		
MAIN SPAN:	OR GIRDER	NGER/MULTI-BEAM APPR. SPAN: NOT APPLICABLE
		TYPE OF SUBSTRUCTURE
ABUTMENTS:	CONCRETE FULL HEIGHT ABUTMI	ENT ON UNKNOWN FOUNDATION
BENTS:	NOT APPLICABLE	
PIERS:	NOT APPLICABLE	
		SCOUR EVALUATION
Bridge has i	inknown foundations. Risk of so	our cannot be determined. The bridge shall be monitored for distress
		e in lieu of installing scour countermeasures.
		INSPECTION PROCEDURES
What Initiated the Call-out Inspection?		[ ] BridgeWatch Alert
		[ ] TDOT District or Local Maintenance Personnel
		[ ] THP or Local Law Enforcement Personnel
		[ ] Other:
		• •
Things to c	heck on a bridge during flood	s:
	movement - horizontally as w	on along curb line, both bridge rails and outer edge of bridge deck.
	Check for plumb of piers or be	
	k for embankment erosion	111.5.
	k for drift build-up on piers or	hents
	• •	nd compare to previous inspection
		report versus current field conditions
[ ] - Kevie	w the latest bridge inspection	report versus current neia conditions
If Closure is	recommended:	
[ ] - Stav	at bridge with vehicle pulled a	cross road until bridge is secured and properly closed by District,
Cour	nty or City Maintenance Perso	nnel. Use Barricade Tape, traffic cones and/or traffic flares as
•	•	rists to stay off of the bridge until such time as the bridge may
-	operly closed and barricaded	
[ ] - Conta	• •	Supervisor (if bridge is State maintained)
		ay Maintenance Official (if bridge is not State maintained)
	• •	atrol and/or local law enforcement Officers as appropriate
	(4) TDOT Regional Bridge	
	<ul> <li>The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.</li> </ul>	

## **PUBLICATION DATE**

## HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	tate District maintenance or local highway maintenance bridge on the selected detour route shall be checked	
<ul> <li>The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.</li> </ul>		
CONTACT PERSONNEL:	TELEPHONE NUMBER:	
REGION BRIDGE ENGINEER	(423) 290-7467	
DISTRICT MAINTENANCE SUPERVISOR	(931) 267-6324	
TENNESSEE HIGHWAY PATROL	(931) 528-8496	
<ul> <li>Summarize and submit findings from the inspection to BridgeWatch scour monitoring system.         The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.     </li> </ul>		
COMMENTS:		
Suggested List of Equipment to conduct the Inspectatest Bridge Inspection Report	ection:	
Scour POA Report with the above Checklist		
Bridge Design Plans, if available		
Tape measure with weight		
Plumb bob		
Range Pole		
A 1000 Foot Roll of yellow Polyethylene Barricade	Tape printed with the following message:	
SAFETY HAZARD KEE	EP AWAY	

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

**TDOT radio directory (State Personnel only)**