HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 68017880003

BRIDGE OWNER: PERRY COUNTY

ROAD NAME: SUGAR HILL RD

CROSSING: BUFFALO RIVER

LATITUDE:: N 35.54467 DEGREES
LONGITUDE: W 87.81993 DEGREES

COUNTY: PERRY
ROUTE: 01788
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 2.44
YEAR BUILT: 1968

LON	GITUDE: W 87.81993 DEGREES	3	YEAR BUILT: 1968		
		TYPE OF SUPERSTRUCTURE			
MAIN SPAN:	STEEL CONTINUOUS - STRINGER/	MULTI-BEAM OR APPR. SPAN:	NOT APPLICABLE		
		TYPE OF SUBSTRUCTURE			
ABUTMENTS:	JTMENTS: CONCRETE STUB ABUTMENT ON STEEL PILE FOUNDATION				
BENTS:	NOT APPLICABLE				
PIERS:	CONCRETE HAMMERHEAD PIER O	N STEEL PILE FOUNDATION			
		SCOUR EVALUATION			
	our critical; bridge foundations de sures are installed but they are r		lculated scour conditions. No scour		
		INSPECTION PROCEDURES			
What Initiated the Call-out Inspection?		[] BridgeWatch Alert			
	·		al Maintenance Personnel		
		[] THP or Local Law En			
		[] Other:			
[] - Span 1. C 2. C [] - Chec [] - Chec [] - Chec	heck on a bridge during flood movement - horizontally as w check displacement / deflection check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, and	ell as vertically n along curb line, both bridg nts. bents nd compare to previous insp			
f Closure is	recommended:				
Coun temp	ty or City Maintenance Persoi	nnel. Use Barricade Tape, tra rists to stay off of the bridge	cured and properly closed by District, ffic cones and/or traffic flares as until such time as the bridge may		
[] - Conta	ct: (1) District Maintenance Supervisor (if bridge is State maintained)				
	(2) City or County Highwa	y Maintenance Official (if b	ridge is not State maintained)		
	(3) Tennessee Highway P	atrol and/or local law enforce	ement Officers as appropriate		
	(4) TDOT Regional Bridge	Engineer			
	 The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team. 				

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	ning a detour route. Any brid	District maintenance or local highway maintenance lge on the selected detour route shall be checked		
[] - The bridge can be r units and they are o	The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.			
CONTACT PERSONNEL	1	TELEPHONE NUMBER:		
COUNTY MAYOR'S OFF	ICE	(931) 589-2216		
HWY. CHIEF ADMINISTR	ATOR'S OFFICE	(931) 589-5217		
COUNTY SHERIFF'S OF	FICE	(931) 589-8803		
The report shall incl	Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:				
Suggested List of Equipm Latest Bridge Inspection I	ent to conduct the Inspectio	<u>en:</u>		
Scour POA Report with th	<u>-</u>			
Bridge Design Plans, if av	ailable			
Tape measure with weigh	t			
Plumb bob				
Range Pole				
A 1000 Foot Roll of yellow		pe printed with the following message:		
	SAFETY HAZARD KEED A	AWAY		

PUBLICATION DATE

A roll of Duct Tape

A Barricade Tape Dispenser with serrated cutter

TDOT radio directory (State Personnel only)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

Traffic Cones - Minimum of four (4)

07-Nov-24