HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 68SR0130017						COUNTY:	PERRY	
BRIDGE OWNER: STATE OF TENNESSEE			INESSEE			ROUTE:	SR013	
ROAI	D NAME:	SR13	3				SPECIAL CASE:	0
CRO	OSSING:	BUF	FALO RIVE	ER			COUNTY SEQUENCE:	1
LA	TITUDE::	Ν	35.81100	DEGREES			LOG MILE:	28.33
LON	GITUDE:	W	87.77795	DEGREES			YEAR BUILT:	1952
					TYPE OF SUPERS			
MAIN SPAN:	STEEL C GIRDER		INUOUS -	STRINGER/M	ULTI-BEAM OR	APPR. SPAN:	CONCRETE - TEE BEAM	
					TYPE OF SUBST			
ABUTMENTS:	CONCRE	ETE S	TUB ABU	TMENT ON CO		UNDATION		
BENTS:	CONCRETE PILE BENT ON PILE FOUNDATION							
PIERS:	CONCRE	ETE S	OLID SHA	FT PIER ON I	ROCK FOUNDATIO	N		
					SCOUR EVAL			
							red at bridge foundations. are installed but they are no	
					INSPECTION PRO	CEDURES -		
What Initiated the Call-out Inspection? [] BridgeWatch Alert								
					[] TDOT Dis	strict or Loca	al Maintenance Personne	el
					[] THP or L	ocal Law Enf	forcement Personnel	

Things to check on a bridge during floods:

- [] Span movement horizontally as well as vertically
 - 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck.

[] Other: ____

- 2. Check for plumb of piers or bents.
- [] Check for embankment erosion
- [] Check for drift build-up on piers or bents
- [] Check pier exposure, if possible, and compare to previous inspection
- [] Review the latest bridge inspection report versus current field conditions

If Closure is recommended:

- [] Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.
- [] Contact: (1) District Maintenance Supervisor (if bridge is State maintained)
 - (2) City or County Highway Maintenance Official (if bridge is not State maintained)
 - (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate
 - (4) TDOT Regional Bridge Engineer
- [] The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.

PUBI	CA	TIC	DN	DA	ΤE
	 			-	

17-Apr-19

BRIDGE ID 68SR0130017



- [] The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.
- [] The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.

CONTACT PERSONNEL:	TELEPHONE NUMBER:
REGION BRIDGE ENGINEER	(615) 476-8860
DISTRICT MAINTENANCE SUPERVISOR	(931) 242-6042
TENNESSEE HIGHWAY PATROL	(931) 766-1425

[] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.

COMMENTS: _____

Suggested List of Equipment to conduct the Inspection:

Latest Bridge Inspection Report

Scour POA Report with the above Checklist

Bridge Design Plans, if available

Tape measure with weight

Plumb bob

Range Pole

A 1000 Foot Roll of yellow Polyethylene Barricade Tape printed with the following message:

SAFETY HAZARD KEEP AWAY

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)

PUBLICATION DATE