Rev. 07-24-15		WAY BRIDGE SCOUR I OF ACTION REPORT	TN TDOT Department of Transportation	
BRIDGE ID N	IUMBER: 700A2350001		COUNTY: POLK	
BRIDGE	OWNER: POLK COUNTY		ROUTE: 0A235	
ROA	D NAME: LADD SPRINGS RD		SPECIAL CASE: 0	
-	OSSING: MINNEWAUGA CREEK		COUNTY SEQUENCE: 1	
	TITUDE:: N 35.00745 DEGREES		LOG MILE: 2.23	
LON	GITUDE: W 84.68903 DEGREES		YEAR BUILT: <b>1930</b>	
		TYPE OF SUPERSTRUCTURE		
MAIN SPAN:	STEEL - STRINGER/MULTI-BEAM OF	R GIRDER APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBSTRUCTURE		
ABUTMENTS: MASONRY OR CONCRETE BLOCK ABUTMENTS ON UNKNOWN FOUNDATION				
BENTS:	NOT APPLICABLE			
PIERS:	NOT APPLICABLE			
SCOUR EVALUATION				
	nknown foundations. Risk of sco cant flood events. Monitor bridge		oridge shall be monitored for distress termeasures.	
		INSPECTION PROCEDURES		
What Initiated the Call-out Inspection? [] BridgeWatch Alert				
at mitlat			I Maintonanaa Daraannal	
		[ ] IDOI DISTICT OF LOCA	I Maintenance Personnel	

- [] THP or Local Law Enforcement Personnel
- [ ] Other: \_\_

## Things to check on a bridge during floods:

- [] Span movement horizontally as well as vertically
  - 1. Check displacement / deflection along curb line, both bridge rails and outer edge of bridge deck.
  - 2. Check for plumb of piers or bents.
- [ ] Check for embankment erosion
- [ ] Check for drift build-up on piers or bents
- [ ] Check pier exposure, if possible, and compare to previous inspection
- [ ] Review the latest bridge inspection report versus current field conditions

## If Closure is recommended:

- [ ] Stay at bridge with vehicle pulled across road until bridge is secured and properly closed by District, County or City Maintenance Personnel. Use Barricade Tape, traffic cones and/or traffic flares as temporary measures to warn motorists to stay off of the bridge until such time as the bridge may be properly closed and barricaded.
- [ ] Contact: (1) District Maintenance Supervisor ( if bridge is State maintained )
  - (2) City or County Highway Maintenance Official ( if bridge is not State maintained )
  - (3) Tennessee Highway Patrol and/or local law enforcement Officers as appropriate
  - (4) TDOT Regional Bridge Engineer
- [ ] The Bridge should remain closed until the water recedes and a daylight visual inspection is made by a TDOT bridge inspection team.

PUBLICATION DATE

07-Nov-24



- [] The bridge inspection team will work with State District maintenance or local highway maintenance officials in establishing a detour route. Any bridge on the selected detour route shall be checked prior to signing the detour route.
- [] The bridge can be re-opened only after a TDOT bridge inspection team checks the substructure units and they are determined to be structurally stable.

CONTACT PERSONNEL:	TELEPHONE NUMBER:
COUNTY MAYOR'S OFFICE	(423) 338-4527
HWY. CHIEF ADMINISTRATOR'S OFFICE	(423) 338-4177
COUNTY SHERIFF'S OFFICE	(423) 338-4543

[ ] - Summarize and submit findings from the inspection to BridgeWatch scour monitoring system. The report shall include the date and time of the inspection, a brief summary of findings and, as appropriate, photographs of the bridge and stream channel measurements. If significant scouring has occurred, the report shall also be copied to Bridge Inspection Headquarters.

COMMENTS: \_\_\_\_\_

Suggested List of Equipment to conduct the Inspection:

Latest Bridge Inspection Report

Scour POA Report with the above Checklist

Bridge Design Plans, if available

Tape measure with weight

Plumb bob

**Range Pole** 

A 1000 Foot Roll of yellow Polyethylene Barricade Tape printed with the following message:

## SAFETY HAZARD KEEP AWAY

A Barricade Tape Dispenser with serrated cutter

A roll of Duct Tape

Traffic Cones - Minimum of four (4)

Traffic Safety Flares - Minimum of four (4) or set of electronic warning flashers

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)

PUBLICATION DATE