HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



BRIDGE ID NUMBER: 720A1430001
BRIDGE OWNER: CITY OF DAYTON
ROAD NAME: WALNUT GROVE RD
CROSSING: LITTLE RICHLAND CREEK
LATITUDE:: N 35.51753 DEGREES
LONGITUDE: W 85.00002 DEGREES

COUNTY: RHEA
ROUTE: 04199
SPECIAL CASE: 0
COUNTY SEQUENCE: 1
LOG MILE: 0.66
YEAR BUILT: 1969

		TYPE OF SUPER	STRUCTURE -		
MAIN SPAN:	PRESTRESSED CONCRETE CONTI STRINGER/MULTI-BEAM OR GIRDE	NUOUS -	APPR. SPAN:	NOT APPLICABLE	
		TYPE OF SUBS	TRUCTURE -		
ABUTMENTS:	CONCRETE STUB ABUTMENT ON S				
BENTS:		FEEL PILE BENT ON PILE FOUNDATION			
PIERS:	NOT APPLICABLE	_			
		OOOLID EVA	LUATION		
D : 1 .		SCOUR EVAI		L. I. But M.	
•	our critical; bridge foundations de sures are installed but they are r		instable for cal	culated scour conditions. No scour	
		INSPECTION PR	OCEDURES -		
What Initiate	ed the Call-out Inspection?	[] BridgeV	Vatch Alert		
	·	[] TDOT D	istrict or Loca	I Maintenance Personnel	
		[] THP or I	Local Law Enf	orcement Personnel	
		[] Other:			
1. C 2. C [] - Checl [] - Checl	movement - horizontally as we check displacement / deflection check for plumb of piers or be k for embankment erosion k for drift build-up on piers or k pier exposure, if possible, and we the latest bridge inspection	n along curb lin nts. bents nd compare to p	ne, both bridge previous inspe		
f Closure is	recommended:				
Coun temp	ty or City Maintenance Persor	nnel. Use Barric rists to stay off	ade Tape, traf	ured and properly closed by District, fic cones and/or traffic flares as until such time as the bridge may	
[] - Conta	act: (1) District Maintenance S	Supervisor (if b	ridge is State	maintained)	
	(2) City or County Highwa	y Maintenance	Official (if br	idge is not State maintained)	
	(3) Tennessee Highway P	atrol and/or loca	al law enforce	ment Officers as appropriate	
	(4) TDOT Regional Bridge	Engineer			
	Bridge should remain closed u FDOT bridge inspection team.		ecedes and a c	laylight visual inspection is made	

PUBLICATION DATE

HIGHWAY BRIDGE SCOUR PLAN OF ACTION REPORT



	route. Any bridge on the selected detour route shall be checked			
	dge can be re-opened only after a TDOT bridge inspection team checks the substructure nd they are determined to be structurally stable.			
CONTACT PERSONNEL:	TELEPHONE NUMBER:			
CITY MAYOR'S OFFICE	(423) 775-1817			
POLICE OFFICE	(423) 775-8403			
The report shall include the date as appropriate, photographs of the	from the inspection to BridgeWatch scour monitoring system. and time of the inspection, a brief summary of findings and, he bridge and stream channel measurements. If significant rt shall also be copied to Bridge Inspection Headquarters.			
COMMENTS:				
Suggested List of Equipment to condu	ict the Inspection:			
Latest Bridge Inspection Report				
Scour POA Report with the above Che	cklist			
Bridge Design Plans, if available				
Tape measure with weight				
Plumb bob				
Range Pole				
	e Barricade Tape printed with the following message:			
♥/ =	IAZARD KEEP AWAY			
A Barricade Tape Dispenser with serra	ted cutter			
A roll of Duct Tape				
Traffic Cones - Minimum of four (4)				
Traffic Safety Flares - Minimum of four	(4) or set of electronic warning flashers			

TDOT two-way radio (State Personnel only) and/or cellular telephone

TDOT radio directory (State Personnel only)